



Firmware Version: V1.04.02

Prom Code Version:

Published Date: 2019/6/12

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	3
Known Issues:	4
Related Documentation:	4





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.04.02	2019/6/12	DCS-5025L	A1
V1.03.07	2016/5/12	DCS-5025L	A1
V1.02.10	2015/10/01	DCS-5025L	A1
V1.01.05	2015/07/15	DCS-5025L	A1
V1.00.20	2015/05/15	DCS-5025L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

- 1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
- 2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
- 3. Click Browse... and specify the firmware file.
- 3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
	1. Update Mydlink Agent to v2.2.0-b64
	2. Change the default system time to 2019/01/01.
	3. Support digest authentication for Web UI
V1.04.02	4. Upgrade MatrixSSL to v3.9.3 that resolve the vulnerabilities in MatrixSSL.
V1.U4.U2	5. Fixed WPA2 KRACK vulnerability issue.
	6. Re-sign the ActiveX plugin with the new certificate
	7. Re-sign the Java applet with the new certificate
	8. Re-sign the macOS plugin with the new certificate
	1. Update Mydlink Agent to v2.0.20-b22
	2. Upgraded OpenSSL to 1.0.1q
	3. Change the HTTPs self-signed certificate to SHA2 algorithms.
	4. Change the default system time to 2016-01-01
V1.03.07	5. Change the copyright year in the web-UI to 2016.
V1.U3.U7	6. Support to send the email notification to multiple email addresses.
	Note: Multiple recipients must be separated by a semicolon, ';'.
	7. Add the authentication mechanism for CGI command:
	config/stream_info.cgi.
	8. Modify the CSRF response to follow the D-Link CSRF specification.



D-Link DCS-5025L Firmware Release Notes

	1. Update to agent 2.0.19-b85
V1.02.10	2. Adds functionality to prevent CSRF in Web-UI.
	3. If adding an existing user account, the web-GUI now pops-up warning.
	1. Update to agent 2.0.19-b49
V1.01.05	2. Reduced WPS timeout flash time
	3. Added Audio noise filter and changed default volume to 50
V1.00.20	1. Initial Release supporting mydlink Home app

Problems Fixed:

Firmware Version	Problems Fixed
	Add XSS protection mechanism for CGI command
	2. For VGA and QVGA profile settings, resize and crop the video frame to the
	aspect ratio of: 16:9.
	3. Fixed the "RSA-CRT key leaks" issue.
	4. Fixed the "LANDAP stack overflow" issue
	5. Fixed an XSS vulnerability
	6. Fixed an issue that /config/ptz_move.cgi doesn't move the camera view in the
	correct direction if the camera is installed upside down and Flip and Mirror are
	both enabled.
	7. Fixed when flip and mirror the camera image and customize the home
	position, the IP Cam will not go back to the customized home position by
V1.04.02	reboot it.
	8. Fixes Cross Site Request Forgery (CSRF) for FTP setting
	9. Fixes denial of service (DoS) for upload firmware and restore configuration
	10. Remove crossdomain.xml.
	11. Fixed a command injection issue in the change admin's password configuration
	12. Fixed when set motion sensitivity to 0%, the motion alarm still occurs.
	13. Fixed for a buffer overflow issue for passing a large string in the
	WEPEncryption parameter provided to wireless.htm.
	14. Fixed the issue where the device can't obtain DHCP IP when connect to an
	Access Point with Enable "Transfer DHCP Offer to Unicast".
	15. Change the open source to follow the GPLv2.
	1. Fixed an issue where IP Camera blocks CGI request from Chrome and Edge.
V1.03.07	2. Fixed an issue where IP Camera can't auto connect to the specific wireless
	network when it drops wireless connection.





DCS-5025L Firmware Release Notes

	3. Fixed an issue that Time zone setting for Minsk should be GMT+3.
	1. Fix the Device Time Zone mismatch issue.
	2. Fixed IP Cam issue where device fails to connect to wireless network
	when serially connecting to wireless routers using WPS PBC method
	3. Fixed the issue where Direct Mode DHCP server will deliver dynamic IP
V1.02.10	address to the AP Client interface of IP Camera.
	4. Fixed PPPoE auto-reconnect failure when unplug/replug Ethernet cable.
	5. Fixed issue where Direct mode does not work properly when device is
	powered on without Ethernet connection.
	6. Adjusted wlan0_ssid and dcs state value on Bonjour TXT record
V1.01.05	1. Fixed WPS performance with Atheros Chipset Routers
V1.01.05	2. WPS process will return to Direct mode if timeout/failure occurs
V1.00.20	1. Initial Release

Known Issues:

Firmware Version	Known Issues
V1.04.02	Block the web GUI access in Safari 12.
V1.00.20	Continuous Snapshot to FTP will cause loading issues.

Related Documentation:

N/A

