



Firmware Version: V2.16.01
Prom Code Version:
Published Date: 2018/7/19

Content:

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: 3

Known Issues: 4

Related Documentation: 4

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.16.01	2018/7/19	DCS-930L	B1,B2
V2.15.06	2018/1/22	DCS-930L	B1,B2
V2.13.15	2016/7/20	DCS-930L	B1,B2
V2.12.01	2015/10/22	DCS-930L	B1,B2
V2.11.03	2015/9/1	DCS-930L	B1,B2
V2.10.04	2015/6/29	DCS-930L	B1
V2.01.03	2015/2/6	DCS-930L	B1
V2.00b6	2014/7/2	DCS-930L	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V2.16.01	<ol style="list-style-type: none"> 1. Upgrade mydlink agent to 2.2.0-b03n 2. Update ActiveX and Java Applet signing certificate
V2.15.06	<ol style="list-style-type: none"> 1. Upgrade mydlink agent to 2.2.0-b03 2. Change the system default date to 2017/01/01 3. Update the ActiveX and Java Applet with renewed code-signing certificate (validity period of the certificate is from 9/30/2016 to 10/1/2019). 4. Support digest authentication for Web UI
V2.13.15	<ol style="list-style-type: none"> 1. Upgrade mydlink agent to 2.1.0-b27. 2. Change the HTTPs self-signed certificate to SHA2 algorithms. 3. Support Mydlink UID mechanism (mdb get dev_uid) 4. Change the support page hyperlink of Firmware Upgrade web-UI to www.dlink.com. 5. Updated OpenSSL to v0.9.8o. 6. Remove mDNSResponder daemon on the unit. 7. Remove the Bonjour settings from the Network Setup web-UI. 8. Change the default system time to 2016-01-01 9. Update the years in the copyright statement for IP Camera's web-UI to 2016. 10. Add authentication to CGI /config/stream_info.cgi. 11. Offer the password validation on console port. (Console's Password is

	synchronized with the admin's password)
V2.12.01	<ol style="list-style-type: none"> 1. Update mydlink agent to v2.0.19-b54n. 2. The ActiveX and Java Applet signing certificate are updated.
V2.11.03	<ol style="list-style-type: none"> 1. Update mydlink agent to 2.0.19-b54 2. Add the denoise mechanism to reduce the background noise 3. Add the login check mechanism to solve Brute Force Attack issue 4. Add Hardware Version item on the Status page of the camera's web-GUI. 5. Change the model and model number of the UPnP properties. F/W V2.11.03 only supports D-ViewCam version as below or above. <ol style="list-style-type: none"> 1. DCS-100 V3.6.5 + DP V1.6.13 2. DCS-100 V4.0.4 + DP V2.0.15
V2.10.04	<ol style="list-style-type: none"> 1. Update mydlink agent to v2.0.19-b35. 2. Support auto image setting switching mechanism for H/W B1 and B2 (or above) camera lens. (*H/W B2 or above only supports v2.10.04 or above)
V2.01.03	<ol style="list-style-type: none"> 1. Upgrade mydlink agent to v2.0.18-b61 2. Remove SSL, change to support TLS.
V2.00b6	<p>Initial version.</p> <p>F/W v2.00 is not backward compatible to H/W Ax version.</p>

Problems Fixed:

Firmware Version	Problems Fixed
V2.15.06	<ol style="list-style-type: none"> 1. Add XSS protection mechanism for CGI command 2. Fixes Cross Site Request Forgery (CSRF) vulnerability for FTP setting 3. Fixes denial of service (DoS) vulnerabilities for upload firmware and restore configuration 4. Remove crossdomain.xml to fix a security vulnerability issue.
V2.13.15	<ol style="list-style-type: none"> 1. Fixed CSRF vulnerability for the camera's web-UI (Exclude CGI APIs). 2. Fixed the "RSA-CRT key leaks" vulnerability. 3. Fixed the "LANDAP stack overflow" vulnerability. (discovered by search SEARCH-LAB) 4. Remove the "Arbitrary file upload interface" vulnerability. (discovered by search SEARCH-LAB). 5. Fixed an issue that Time zone setting for Minsk should be GMT+3. 6. Fixed a vulnerability - Authenticated Arbitrary File Upload with Root Privileges. (discovered by IOActive Security)

	<ul style="list-style-type: none"> 7. Fixed a vulnerability - Authenticated Root OS Command Injection in File Upload. (discovered by IOActive Security) 8. Fixed an XSS vulnerability - Stored XSS in User Name. (discovered by IOActive Security) 9. Fixed an XSS vulnerability - Reflected XSS in HTTP Host Header. (discovered by IOActive Security)
V2.11.03	<ul style="list-style-type: none"> 1. Fixed the IE11 compatibility issue in Windows 10. 2. Change WPS LED behavior blinking time on WPS error/timeout to 10 seconds. 3. Remove the reboot function by pressing and holding the reset button in less than 3 seconds. 4. Add the pop-up warning message when the user creates an existing user account on Device Web GUI. 5. Support to auto-create FTP folder if the folder doesn't exist on FTP server.
V2.10.04	<ul style="list-style-type: none"> 1. Remove one Hidden webUI. 2. Fixed HTTPS issue that causes Day/Night control not work from portal/app. 3. Fixes the issue in which IP Cam cannot create FTP folder with FTP server on Netgear R7000 Router. 4. Fixed CGI /reset.cgi reboot command not work issue. 5. Modify Time Zone Table list to support some existing time zones changes.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A