



Firmware Version: 1.03B27\_WW

Published Date: March 4, 2011

Copyright © 2011

#### **Copyright Notice**

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

#### **Disclaimer**

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

#### **Limitations of Liability**

UNDER NO CIRCUMSTANCES SHALL D-LINK OR ITS SUPPLIERS BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE D-LINK PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF D-LINK IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, D-LINK WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. D-LINK WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT D-LINK RECEIVED FROM THE END-USER FOR THE PRODUCT.

#### **Content:**

Revision History and System Requirement:	2
Important Notes:	
Notes for Configuration Auto-Backup/Restore in USB Storage	2
Upgrading Instructions:	3
Upgrading by using Web-UI	3
New Features:	3
Changes of MIB & D-View Module:	4
Problems Fixed:	4
Known Issues:	10
Related Documentation:	16





**Revision History and System Requirement:** 

Firmware Version	Region	Date	Model	HW Version
1.03B27_WW	ww	March 4, 2011	DSR-500/500N/1000/1000N	A1
1.03B23_WW	WW	Jan. 31, 2011	DSR-500/500N/1000/1000N	A1
1.03B12_WW	WW	Nov. 22, 2010	DSR-500/500N/1000/1000N	A1
1.02B25_WW	WW	Oct. 11, 2010	DSR-500N, DSR-1000N	A1
1.02B11	WW	August 10, 2010	DSR-500N, DSR-1000N	A1
1.01B50	ww	April 30, 2010	DSR-1000N	A1

### **Important Notes:**

- 1. Automatic factory reset when image upgrade detects a firmware region mismatch between RU and WW images. Such as firmware upgrade from RU->WW or WW->RU image.
- 2. For DSR-1000N 3G feature, it needs to enable and define the type of USB device on the USB Settings page before 3G USB modem can be used.
- 3. Before plug DWM-152/156 3G USB dongle in DSR-1000/1000N, please make sure the SIM Card is Not set PIN code.
- 4. Microsoft Windows XP has some well-known limitation to access USB storage of DSR router, D-Link provides a Registry Script file named: WinXP.reg which can solve limitation of Windows XP environment. Without applying this script file, it cannot copy file from Windows XP to USB storage. (This issue will not happen when copy file from USB storage to Windows XP)

### Notes for Configuration Auto-Backup/Restore in USB Storage

D-Link DSR router series support configuration backup or restore automatically while a USB drive is inserted. Following information instructs what condition will perform backup/restore.

- 1. The router configuration will be automatically backed up to the USB drive as soon as the USB drive is inserted. The back name has format <Model Name>\_<Serial Number>.cfg provided this USB drive doesn't have a backup configuration file from a DSR router already present.
- 2. The system LED on the router blinks 3X in amber to indicate a backup operation has started.
- 3. The configuration in the USB drive can be updated if the user manually clicks 'Save Settings' in any GUI page and provided the Model Number and the Serial Number of the router matches with the file already present in the USB drive.
- 4. In case of reboot, the router checks for the presence of configuration file (with format ModelName\_SerialNumber.cfg). If found, the configuration from the USB drive is restored on the router. If a configuration file with the correct format is present in both connected USB drives, the configuration from the first USB drive will be used to restore the router.
- 5. The USB drive can have only one configuration with the above mentioned format for each model name.



### **Unified Services Router Release Notes**



6. If the USB drive is plugged in to the router which is in factory default state, then during reboot, no backup is taken since no custom configuration file exists in the router by that time. The custom configuration is stored on the USB drive once the user clicks Save Settings in any GUI page.

### **Upgrading Instructions:**

#### **Upgrading by using Web-UI**

Please use GUI upgrade feature to upgrade to this firmware version. For detailed installation and upgrade instructions, please refer to the Firmware Upgrades chapter in the *Unified Services*\*Router v1.02 User Manual.

#### **New Features:**

Firmware	New Features
Version	
1.03B27_WW	<ol> <li>Support WMM (Wi-Fi Multimedia) for DSR-500N and DSR-1000N.</li> <li>Support OpenVPN.</li> <li>Authentication and encryption method is modifiable in PPTP and L2TP.</li> <li>Support customized login page for captive portal.</li> <li>Captive Portal can take effective by different individual VLANs.</li> <li>Support private MIB for LEDs indicators of front panel.</li> </ol>
1.03B23_WW	<ol> <li>Support IKEv2.</li> <li>Support L2TP over IPSec.</li> <li>Support configuration auto-backup/auto-restore while a USB drive is inserted. Please refer to the implementation note for more detail of this document on page 2.</li> <li>Support SSL VPN CLI.</li> <li>Support Easy-Setup VPN feature. The benefit of this feature is that HQ IT/MIS can manually write a specific format file then deliver to non-IT background users of remote office. When the user imported this specific file in remote DSR router, all necessary VPN setting would be finished and ready for VPN tunnel establishment between HQ central site and remote offices.</li> <li>Support Intel AMT reflector.</li> </ol>
1.03B12_WW	<ol> <li>Support Non-Split tunnel for IPSec VPN.</li> <li>Support USB storage and printer sharing.</li> <li>Improve WAN configuration page based on drop-down menu.</li> <li>Support logging for SSL VPN activity.</li> <li>Support Interoperability with Cisco VPN client in iPhone OS4.</li> <li>Support NAT hair-pinning.</li> <li>Reverse the logs display, so that the latest logs are shown at the top of the viewer.</li> <li>Support DWM-152/156 A3 3G USB dongle. (This only affects in</li> </ol>







	DSR-1000/1000N)
	9. Support for enable / disable Jumbo frames.
	10. Support for add / edit / delete routing table of secondary PPPoE tunnel.
	11. Spill over mode improvements - configurable maximum WAN bandwidth and load tolerance.
	12. Support captive portal.
	13. Support Blowfish and CAST-128 encryption-authentication algorithms in IKE Policy Configuration page.
	14. Support for IPSec policy option for AH alone (without ESP)
	15. Support for temporary blocking of user login for brute password attack.
	16. Available to choose the local traffic selector in VPN Wizard page.
	1. Added support for Russia PPTP/L2TP Dual Access.
	2. Support IPSec Failover
1.02B25_WW	3. Support for DWM-152/156 A1/A2 3G USB dongles with firmware 1.03 and 1.05
	4. Added support for RFC 3442 for DHCP client
1.02B11	SSL VPN module upgrade to support SSL VPN on Windows 7 and Mac 10.6 operating systems
	It's the first release.
1.01B50	

### **Changes of MIB & D-View Module:**

DSR series can support LED MIB from firmware v1.03B27 and later.

### **Problems Fixed:**

Firmware Version	Problems Fixed
	1. Fix USB Storage sharing is accessible from WAN.
	2. Device blocking DMZ to WAN traffic when captive portal authentication is
	enabled on default VLAN(LAN).
1.03B27_WW	3. Captive Portal feature will block users accessing internet through IPSEC
	VPN and SSL VPN tunnel.
	4. CLI is prompting for prefix in ipv4 static routing configuration.
	5. User is unable to set the exchange mode as Aggressive using CLI while



# **D-Link**® Unified Services Router Release Notes

	adding IPSec VPN policy.
	6. User able to add group based SSL VPN policy for not existed group from CLI.
	7. Device is accepting the SSL VPN Client IP address range which is in the LAN
	subnet from CLI.
	8. IKEv2 is unable to establish the tunnel when WAN cable unplug and plug it
	back.
	9. It's not able to establish VPN tunnel with Extended Authentication as Edge
	device using Easy-Setup VPN import file.
	10. After delete same self certificate and reboot, device is not showing error
	message while deleting CA cert.
	11. The Java console of SSL VPN client is showing DES as cipher suite for SSL
	VPN tunnel.
	12. Observed critical error in browser login page when user entered URL
	"https:// <lan ip="">/scgi-bin/platform.cgi/".</lan>
	13. Need to update User Policy By Client Browser with IE, Firefox, Opera and
	Chrome" only.
	14. Device is not throwing correct error message when user login wrong portal
	name.
	15. Need to restrict the WebUI access using remote management port from
	LAN side.
	16. It's able to change the default domain, group and user configuration
	through CLI.
	17. Current Web GUI session of logged in user is not terminating after
	changing password through CLI.
	18. IKEv2 Traffic Selector Type: Range is not supporting.
	19. PPTP Server have no option to disable MPPE encryption.
	20. Need to change help content in DMZ page.
	21. Device is not showing portal layout URL IP address as "0.0.0.0".
	1. Problem routing TCP traffic in VPN tunnel.
1.03B23_WW	2. USB printer sharing will not work after manually reboot.
1.03b23_WW	3. Inbound Intel AMT feature is not working in load balancing mode.
	4. It's not able to block ICMP traffic using SSL VPN policy.
	1. Device displaying local server IP in GUI after changing the firewall rules
	from allow always to block always.
1.03B12_WW	2. Device not displaying "Local1-UTM" option at SysLog Facility options in
	remote logging configuration page.
	3. Improve Japanese Multiple PPPoE usability issue.



- 4. Manually Configured "Use These DNS Server", DNS is not updating for PPPoE/Japanese multiple PPPoE ISPs.
- 5. Block user access to Captive Portal login page, when Captive Portal is disabled.
- 6. Adding USB storage and Printer help pages.
- 7. USB1 status not being updated dynamically.
- 8. Print jobs are not being deleted after the print is done.
- 9. User is able to upload more than one active self cert in Authentication page causing "critical error" in linux firefox and blank page in "opera".
- 10. USB storage does not work after reboot.
- 11. Fixed firewall dependencies on USB storage and Printer.
- 12. Able to access the data from Linux host even after clicking 'Safely Removed' button for USB storage.
- 13. Increase range for retry interval of WAN failover between 5 to 999 seconds.
- 14. Observed kernel dump due to unaligned memory access while removing the 3G USB dongle (unmounted incorrectly)
- 15. WEP key doesn't support ASCII. (This only affects wireless models)
- 16. Duplicate domain names are showing in domain drop down if users add custom group in group pages.
- 17. Device does not send DHCP release to DHCP server (after soft reboot).
- 18. Error message displayed and redirected to add VLAN page on checking the Inter VLAN Routing button in default VLAN.
- 19. Device is not accepting more than 15 characters in 'Server address' field in WAN1 setup page.
- 20. SSL VPN performance optimizations.
- 21. It's not able to establish Gateway-to-Gateway IPSec VPN with Phase 2 encryption algorithm as "None".
- 22. 'Default admin user' session is getting terminated after login to the DUT with 'custom admin user' from LAN/WAN side.
- 23. It fails to import CSV file of DOS format.
- 24. Sometimes 3G network is not connecting when plug-out & plug-in the card multiple times.
- 25. Update Help Pages for WAN configuration pages.

#### 1.02B25 WW

- 1. Current guest session is not logging out even if we change the password using admin account from same/different host.
- 2. Change the "Enter Your Password" field as "Enter Current Logged in Administrator Password" in edit users page.



# **D-Link** Unified Services Router Release Notes



- 3. Able to add protocol binding rule for same service on all WANs in load balancing mode.
- 4. DHCP relay issues when user configures more than 4 VLANS to DHCP relay.
- 5. Router is not accepting local/remote traffic selector IP with 4th octet value as other than '0' (zero).
- 6. User able to configure Primary and secondary wan with same pptp/l2tp credentials.
- 7. Clone your MAC address option doesn't work for WAN2.
- 8. Need to add validation in Approved URL page.
- 9. After enabling all logging options and device name with max special characters, if user change the lan subnet then it won't reflect in GUI and backend.
- 10. User is able to configure the WAN1/WAN2/DMZ ip address as loop back (127.0.0.1) address.
- 11. Error message displayed and redirected to add vlan page on checking the Inter-VLAN routing button in default VLAN.
- 12. DUT is accepting more than 64 characters at Username, Domain name and Password fields in Dynamic DNS page.
- 13. Observed critical error in WebUI after manually removing USB and if user tries to refresh the browser.
- 14. User not able to enable WPS for WPA and WPA2 security mode and "wsccmd" processes in Zombie state while enabling the WPS.
- 15. Device is not showing ipv6 gateway IP in Device status page.
- 16. Device is throwing wrong error message while adding an entry without any name in IP/MAC binding configuration page.
- 17. Device is accepting duplicate IP and MAC entries in IP/MAC binding configuration page.
- 18. In static routes for Ipv6. Subnet validation is not happening for routes with interface as Wan2.
- 19. User should not able to configure PPTP/L2TP server's Starting IP Address and Ending IP Address in the subnet of LAN/VLAN/DMZ.
- 20. Dash board GUI issues in different browsers with multiple applications when we select different interface in Russia image.
- 21. Support Maximum characters limit check for Names fields In Users, Domains , Groups pages, SSL Resources, SSL Portforwarding.
- 22. Device Displaying "Specified portal not found" when configure portal layout name with maximum special and legal characters





	23. Device is sending the DPD packets to the remote wan of VPN gateway after every 5 seconds.
	24. Device showing "null" in wan connection status when no cable connected
	to interface and wan mode in idle.
	25. DSR-500N default channel is changed to 6.
	26. if SSL username contains special characters, Device displaying white blank
	page instead of client portal page.
	27. Generate self certificate request should have signature key length 2048 bits
	28. Portforwarding tunnel not establishing in java based browsers.
	29. While establishing SSL VPN, Strongest cipher suit selection is desired from
	SSL server.
	30. USB settings page not showing correct status for 3G
	Device exposing LAN host IP as terminator: in remote login page
	1. Same SSID can be configured for two different APs (should be prevented)
	2. Domain name is not coming with asterisk sign(*), if we made custom portal as default.
	3. Duplicate domain names are showing in domain drop down if we add
	custom group in group pages.
	4. Scalability Issue - Admin can add more than maximum users limit.
	5. Displaying html code in GUI page when user tries configure pppoe profile
	with all special characters.
	6. Need IP address validation in NTP page.
	7. Device not displaying vlan's lease information in DHCP leased clients page.
	8. Device not displaying correct IPV6 DNS information in Device status page.
1.02B11	9. Primary and secondary DNS server fields in LAN IPv6 page are not grayed out when user select "Use DNS from ISP" option.
	10. When VLAN is disabled, other options in VLAN pages are not grayed out.
	11. SSL External Authentication with LDAP is not working.
	12. LAN's IPv6 address is getting configured wrongly.
	13. Changing LAN IP doesn't restart DHCP server.
	14. Issue with port '0' in custom service.
	15. RDP or VNC over load balancing (incoming) is not working after 30+ min.
	16. Crash with ixChariot heavy traffic + USB continuous read/write operations
	(simulate full load DVT testing) and also observed kernel dump when
	runnning traffic between WLAN clients.
	17. Device not displaying device statistics when wan connected with PPP link.
dlinkigreen	



# **D-Link**® Unified Services Router Release Notes

	18. SSLVPN tunnel getting dropped in 3 minutes with Linux OS.
	19. Observed unknown WINS server and DNS server information while
	connecting L2TP client to DSR1000N router as L2TP server.
	20. Without sending terminal-request packet when L2TP tunnel manually
	disconnected.
	21. Device taking around 90 seconds login after factory reset from GUI.
	22. DWA-160 can't connect to DSR-1000N with WPS.
	23. WAN2's IPv6 address is empty in GUI.
	24. User not able to add the multiple set of source and destination users in
	firewall page.
	25. When WAN1 is configured as L2TP and WAN2 is configured as any link
	types, Auto-Failover is not working with failure detection method with
	Default/Custom DNS.
	26. WiFi Clients are not associating to AP when Pre-authentication is enable.
	27. In all auto refresh pages, Device showing 5 seconds instead of 10 seconds
	after user tries to configure invalid pool interval time.
	28. No validations for ISATAP subnet prefix in ISATAP Tunnels page.
	29. "Display the IPv6 Routing Table" should grayed out in IPV4 mode.
	30. Wan mode switching (WAN1 <=> WAN2) is not reflecting at backend.
	31. WiFi frequency is not changing from 2.4 GHz to 5 GHz when using CLI
	1. Device displaying inaccurate error message like "SSL-VPN client pool is also
	in the same range. Please configure different IP." When user configure the
	LAN DHCP server page with alphabets "abc.cde.fgh.ijk".
	2. Device allows user to configure other special characters in
	primary/secondary NTP server fields.
	3. Device displaying wrong error message while uploading Firmware via USB
	page without selecting any file.
	4. After configuring resource for subnet, if user add the single IP address,
1.01B50	device displaying the previous IP network subnet mask in GUI.
1.01050	5. User should not be able to configure the SSLVPN client LCP time out as "0".
	6. Look GUI and feel issue when "help" is clicked in SSLVPN portal pages.
	7. Validation needed for IPv6 Advertisement prefixes page.
	8. The USB page shows wrong icons initially for an instant, then displays
	correct icons.
	9. WAN is not coming up automatically if cable removed before upgrade from
	B42 to B48, user must enable WAN from GUI.
	10. DUT can't reset to default. Wireless client not disconnect from DUT when
	push the reset button.



11. Wireless DHCP clients can't get correct IP address from VLAN.

### **Known Issues:**

Firmware Version	Known Issues
	1. There is an issue where the router is not able to transfer files > 250MB from
	Windows XP to USB storage after apply WinXP.reg script file.
	2. IPSec, SMTP and DNS ALG are not working correctly (IPSec pass-through is
	OK).
	3. Transparent mode, observe ARP flooding on eth2.
	4. SNMP system alarm traps are not supported.
	5. Voice at LAN side client is not heard when the SIP Proxy resides in LAN.
	6. VLAN uptime counter not being displayed.
	7. Voice between LAN side SIP clients are not clear when Ixia traffic is running
	between LAN to LAN.
	8. WAN port duplex settings issue.
	9. LAN side VLC Receiver does not receive multicast traffic from VLC sender
	when DUT is behind NAT router.
	10. GUI dropdown does not contain these pre-defined services: AOL,
	DHCP-Relay, Syslog, SQN-netv1, SQN-netv2, TCP-ANY, NetMeeting,
1.03B23	H.323, L2TP, NTP, LDAP, Real video, Real Media Firewall.
	11. Device is not displaying correct MTU size for PPP interfaces.
	12. Secondary PPPoE profile is not coming up automatically once it goes down
	for Japanese Multiple PPPoE.
	13. Daylight saving with manual settings is not working properly for
	Newfoundland and Greenland time zones.
	14. Observed "Critical error" in GUI when user trying with wrong URL
	"https://192.168.10.1/scgi-bin/platform.cgi/page=page".
	15. PPTP pass-through is not taking highest priority than PPTP firewall service.
	16. IPSec pass-through is not taking highest priority than IKE outbound
	firewall service.
	17. Device is allowing XAUTH users to login to CLI.
	18. Not exchanging routes with RIP-2B that have 'Metric' value as 4/5/6.
	19. It's able to configure the same MAC address to WAN1 and WAN2 ports by
Barrier Land	selecting the 'Clone your PC's MAC Address' option.
	20. When IPv6 WAN is configured as static, router is not configuring IP using



# **D-Link**® Unified Services Router Release Notes



prefix advertisement.

- 21. After editing the WEP profile(wep-64), another WEP profile (wep-128) wireless client is not reconnecting until disable/enable the corresponding AP.
- 22. PPTP connection using MAC of WAN PHYs as gateway, it isn't correct behavior.
- 23. Firewall has the highest priority than content filtering ->approved URL.
- 24. Blank field for "data to supply to CA" when click view button in Self certificates requests page.
- 25. VLAN dropped in and dropped out packet entries are incorrect in dashboard page.
- 26. WLAN PC can't play multicast stream.
- 27. User cannot enable UPnP on LAN and VLAN simultaneously.
- 28. With the D-Link DWA-160 Xtream N Dual Band USB adapter, the WPS status displays 'Failed' in the device WPS page, even though client is connected successfully.
- 29. Bandwidth rules over IPSec VPN tunnel are not being followed.
- 30. Need to fine tune BPDU and 802.1X according to the D-Link standard.
- 31. The progress bar in firmware page is not always consistent with the image upload process.
- 32. Device keep on sending syslogs to syslog server after removing the earlier configured syslog server IP address.
- 33. Mismatch between configured and transmit power shown.
- 34. Need to update help content regarding system name without dot(.) information in Admin Settings page.
- 35. Transparent mode functionality is not working on WAN2.
- 36. USB LED is taking 20 seconds to glow for DWM-152/156 with firmware v1.03.
- 37. External Authentication support in CaptivePortal is not available.
- 38. USB storage is not working perfectly with windows XP. It's not able to open files without copying them locally and it has issue to copy larger files from Network Storage share on to the Windows XP host.
  - (Note: 1. Copy files from Windows XP to Network Storage works fine. 2. This issue doesn't affect Windows Vista, Windows 7 and Linuc based operating systems)
- 39. It's Not able access the Intel AMT client located at LAN side from Intel AMT server at WAN side after turned off the Intel AMT.
- 40. Device should show only 50 users per page and there should be a link to





	next page in bottom of the user table.
	1. IPSec, SMTP and DNS ALG are not working correctly (IPSec pass-through is
	OK).
	2. SNMP system alarm traps are not supported.
	3. Voice at LAN side client is not heard when the SIP Proxy resides in LAN.
	4. VLAN uptime counter not being displayed.
	5. Voice between LAN side SIP clients are not clear when Ixia traffic is running
	between LAN to LAN.
	6. WAN port duplex settings issue.
	7. LAN side VLC Receiver does not receive multicast traffic from VLC sender
	when DUT is behind NAT router.
	8. GUI dropdown does not contain these pre-defined services: AOL,
	DHCP-Relay, Syslog, SQN-netv1, SQN-netv2, TCP-ANY, NetMeeting,
	H.323, L2TP, NTP, LDAP, Real video, Real Media Firewall.
	9. Device is not displaying correct MTU size for PPP interfaces.
	10. Secondary PPPoE profile is not coming up automatically once it goes down
	for Japanese Multiple PPPoE.
	11. Daylight saving with manual settings is not working properly for
1.03B12_WW	Newfoundland and Greenland time zones.
	12. Observed "Critical error" in GUI when user trying with wrong URL
	"https://192.168.10.1/scgi-bin/platform.cgi/page=page".
	13. PPTP pass-through is not taking highest priority than PPTP firewall service.
	14. IPSec pass-through is not taking highest priority than IKE outbound
	firewall service.
	15. Device is allowing XAUTH users to login to CLI.
	16. Not exchanging routes with RIP-2B that have 'Metric' value as 4/5/6.
	17. It's able to configure the same MAC address to WAN1 and WAN2 ports by
	selecting the 'Clone your PC's MAC Address' option.
	18. When IPv6 WAN is configured as static, router is not configuring IP using
	prefix advertisement.
	19. After editing the WEP profile(wep-64), another WEP profile (wep-128)
	wireless client is not reconnecting until disable/enable the corresponding
	AP.
	20. PPTP connection using MAC of WAN PHYs as gateway, it isn't correct
	behavior.
	21. Firewall has the highest priority than content filtering ->approved URL.
	22. Blank field for "data to supply to CA" when click view button in Self





certificates requests page.

- 23. VLAN dropped in and dropped out packet entries are incorrect in dashboard page.
- 24. Problem routing TCP traffic in VPN.
- 25. WLAN PC can't play multicast stream.
- 26. User cannot enable UPnP on LAN and VLAN simultaneously.
- 27. With the D-Link DWA-160 Xtream N Dual Band USB adapter, the WPS status displays 'Failed' in the device WPS page, even though client is connected successfully.
- 28. Bandwidth rules over IPSec VPN tunnel are not being followed.
- 29. Need to fine tune BPDU and 802.1X according to the D-Link standard.
- 30. The progress bar in firmware page is not always consistent with the image upload process.
- 31. Device keep on sending syslogs to syslog server after removing the earlier configured syslog server IP address.
- 32. Mismatch between configured and transmit power shown.
- 33. Need to update help content regarding system name without dot(.) information in Admin Settings page.
- 34. Transparent mode functionality is not working on WAN2.
- 35. USB LED is taking 20 seconds to glow for DWM-152/156 with firmware v1.03.
- 36. USB storage is not working perfectly with windows XP. It's not able to open files without copying them locally and it has issue to copy larger files from Network Storage share on to the Windows XP host.
  - (Note: 1. Copy files from Windows XP to Network Storage works fine. 2. This issue doesn't affect Windows Vista, Windows 7 and Linuc based operating systems)
- 1. Transparent mode, observe ARP flooding on eth2.
- 2. Voice between LAN side SIP clients are not clear when Ixia traffic is running between LAN to LAN.
- 3. WAN port duplex settings issue.
- 4. Observed kernel dump due to unaligned memory access while removing the 3G USB dongle (unmounted incorrectly).
- 5. DUT is not displaying correct MTU size for PPP interfaces.
- 6. Second PPPoE profile not coming up automatically once it goes down
- 7. Daylight saving with manual settings is not working properly for Newfoundland and Greenland timezones.
- 8. Wireless TCP receive side throughput performance with Veriwave is not

### 1.02B21





	good (IxChariot & over-the-air is OK)
	9. DUT is allowing XAUTH users to login to CLI.
	10. Not exchanging routes with RIP-2B that have 'Metric' value as 4/5/6
	11. User able to configure the same MAC address to WAN1 and WAN2 ports by
	selecting the 'Clone your PC's MAC Address' option.
	12. When IPv6 WAN is configured as static, router is not configuring IP using
	prefix advertisement.
	13. Device not displaying valid error message when l2tp, pptp, xauth, local
	users tries to login with user name password.
	14. Help text related issues in DSR-1000N and DSR-500N.
	15. Device taking long time to open the status -> Lan clients page.
	16. PPTP connection using MAC of WAN PHYs as gateway, it isn't correct behavior.
	17. Device does not send DHCP release to DHCP server (after soft reboot).
	18. Firewall has the highest priority than content filtering ->approved URL.
	19. Blank field for "data to supply to CA" when click view button in Self
	certificates requests page.
	20. VLAN dropped in and dropped out packet entries are incorrect in
	dashboard page.
	21. Problem routing TCP traffic in VPN.
	22. WLAN PC can't play multicast stream.
	23. Mismatch between configured and transmit power shown
	24. Need to update help content regarding system name without dot(.)
	information in Admin Settings page.
	25. It cannot support DWM-152/156 with hardware version A3.
	26. Transparent mode functionality is not working on WAN2
	27. USB led is taking 20sec to glow for fw1.03.
	28. In CLI, options should also be shown depending upon the access
	specifications.
	29. Dash board GUI issues in different browsers with multiple applications
	when we select different interface in Russia image.
	1. IPSec, SMTP and DNS ALG's not working correctly (IPSec Pass-through is
	OK)
1.01050	2. Runtime authentication support is not available.
1.01B50	3. Transparent mode, observe ARP flooding on eth2
	4. Voice of SIP clients is not clear between LAN sides when Ixia traffic is
	running between LAN to LAN.



### **D-Link** Unified Services Router Release Notes



- 5. Current guest session is not logging out even if we change the password using admin account from same/different host.
- 6. Need to add Maximum characters limit check for Names fields In Users, Domains, Groups pages, SSL Resources, SSL Port forwarding.
- 7. WAN port duplex settings issue.
- 8. Observed kernel dump due to unaligned memory access while removing the 3G USB dongle (Un-mounted incorrectly)
- 9. LAN side VLC Receiver does not receive multicast traffic from VLC sender when DUT is behind NAT router.
- 10. GUI dropdown does not contain these services: AOL, DHCP-Relay, Syslog, SQN-netv1, SQN-netv2, TCP-ANY, NetMeeting, H.323, L2TP, NTP, LDAP, Real video, Real Media Firewall.
- 11. DUT is not displaying correct MTU size for PPP interfaces.
- 12. Second PPPOE profile not coming up automatically once it goes down.
- 13. Daylight saving with manual settings is not working properly for Newfoundland and Greenland Time Zones.
- 14. Dashboard is not displaying recently browsed websites.
- 15. DUT is allowing XAUTH users to login to CLI.
- 16. Not exchanging routes with RIP-2B that have 'Metric' value as 4/5/6
- 17. User able to configure the same MAC address to WAN1 and WAN2 ports by selecting the 'Clone your PC's MAC Address' option.
- 18. Device Displaying "Specified portal not found" when configure portal layout name with maximum special and legal characters.
- 19. Need to display status for second PPPoE tunnel.
- 20. When IPv6 WAN is configured as static, router is not configuring IP using prefix advertisement.
- 21. Device not displaying valid error message when L2TP, PPTP, xAuth, local users tries to login with user name password.
- 22. Domain name is not coming with asterisk sign(\*), if we made custom portal as default.
- 23. Device taking long time to open the Status -> LAN clients page.
- 24. User able to upload the invalid CSV file which has group with wrong domain name.
- 25. Device doesn't send DHCP release to DHCP server (after soft reboot).
- 26. Firewall rules should have the highest priority than Web content filtering when configuring approved URLs.
- 27. Blank field for "data to supply to CA" when click view button in Self certificates requests page.





### **Unified Services Router Release Notes**

- 28. Support for Add/Edit secondary tunnel routing table
- 29. VLAN dropped in and dropped out packet entries are incorrect in dashboard page.
- 30. Support for USB LED to indicate Link Activity
- 31. Support terminal request packet when L2TP tunnel manually disconnected.
- 32. It has some problems to route TCP traffic in VPN.
- 33. DWA-160 can't connect to DSR-1000N with WPS feature.
- 34. WLAN PC can't play multicast stream.
- 35. WAN2's IPv6 address is empty in GUI.
- 36. LAN's IPv6 address is getting configured wrongly.

### **Related Documentation:**

- Unified Services Router User Manual v1.02
- Unified Services Router CLI Reference Guide v1.02

