



Firmware Version: V1.02.02
Prom Code Version:
Published Date: 2016/1/29

Content:

Upgrading Instructions:..... 2
New Features:..... 2
Problems Fixed: 2
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

| Firmware Version | Date | Model | Hardware Version |
|------------------|------------|-----------|------------------|
| V1.02.02 | 2016/1/29 | DCS-2630L | A1 |
| V1.01.02 | 2015/10/06 | DCS-2630L | A1 |
| V1.00-1221 | 2015/8/20 | DCS-2630L | A1 |
| | | | |

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

| Firmware Version | New Features |
|------------------|---|
| V1.02.02 | <ol style="list-style-type: none"> 1. Support CSRF protection. 2. Update mydlink agent to version 2.0.20-b15 3. The HTTP Authentication Realm will change as "Product_Name_xx", where xx is 2 digit suffix of MAC address. (To fix the CSRF vulnerability) 4. Reduce the time of WiFi connection setup from App. 5. Increasing the success rate of WPS connection setup. 6. Refine RTP/RTSP. 7. Enhance wireless performance. 8. Add dewarp offset calibration. |
| V1.01.02 | <ol style="list-style-type: none"> 1. Updated mydlink agent to V2.0.19-b79 2. Added 3DES support, removed RC4 support (for security purposes) 3. Added warning message for Chrome users (due to NPAPI disable) 4. Updated MAC plugin 5. Changed Firmware naming method 6. Added support for Direct Mode spec 0.81 7. Security enhancements for CSRF |
| V1.00-1221 | Initial Release. mydlink agent v2.0.19-b44 |
| | |

Problems Fixed:

| Firmware Version | Problems Fixed |
|------------------|----------------|
| | |

| | |
|----------|---|
| V1.02.02 | <ol style="list-style-type: none"> 1. Check DUT CSRF protection issue, DUT web UI could be browsed with incorrect http referer and didn't need authentication. 2. Firefox plug is busy easily when viewing the live streaming with 1920x1080. 3. Show real MAC address in status page whatever using client mode or direct mode connection. 4. DUT couldn't wireless connect to DIR-880L when DUT security mode is WPA-PSK and cipher type is TKIP/AES. 5. DUT RTSP stream 2 have no audio. 6. After upload signed certificate, DUT would show doesn't match with original certificate request. 7. DUT motion detection trigger time is the second snapshot rather than the fourth snapshot. |
| V1.01.02 | <ol style="list-style-type: none"> 1. Refine the wording from "Router Setup" to "Wireless Setup". 2. Restore the AP mode SSID/Password after loading other device's configuration. 3. Resolved mydlink push/email notification function problem. 4. Correct TZ and DST information. |
| | |
| | |

Known Issues:

| Firmware Version | Known Issues |
|------------------|--------------|
| | |
| | |

Related Documentation:

N/A