



**Firmware Version:** V1.12.02  
**Prom Code Version:**  
**Published Date:** 2015/3/6

---

**Content:**

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: ..... 3

Known Issues: ..... 4

Related Documentation: ..... 4

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.12.02	2015/3/6	DCS-6010L	A1, A2
V1.11.00	2014/12/24	DCS-6010L	A1, A2
V1.10.01	2014/11/25	DCS-6010L	A1, A2
V1.02.00	2013/7/29	DCS-6010L	A1
V1.01.18	2013/6/18	DCS-6010L	A1

## Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

## New Features:

Firmware Version	New Features
V1.12.02	1. Update the mydlink agent to 2.0.19-b02
V1.11.00	1. Update the mydlink agent to 2.0.18-b54 2. Disable the SSL2.0/3.0 3. Disable the RC4/DES
V1.10.01	1. Update the mydlink agent to 2.0.17-b76 2. Meet new EU wireless regularization EN300 328 v1.8.1 3. Support MP4 recording format 4. Added Schedule Reboot function 5. Added the exposure mode "Customize1~3" options 6. Support motion detection feature on non-IE browser 7. Add 50MB/30 sec Event on SD function 8. Add new DDNS selection
V1.02.00	1. Update the mydlink agent to 2.0.17-b18 2. Support 2-way audio function at portal and APP 3. Support onvif test tool V12.06 4. Add the Home position set by user.
V1.01.18	<b>The Firmware is only supported by wizard v1.04.02 or above.</b> Upgrade to UPnP v1.6.18.

## Problems Fixed:

Firmware Version	Problems Fixed
V1.12.02	<ol style="list-style-type: none"> <li>1. Fixed the 2-way audio failed issue on iOS8</li> <li>2. Fixed the issue of faulty auto-firmware upgrade mechanism</li> <li>3. Fine-tune the wireless performance</li> <li>4. Fixed the issue found no video streaming when the device was boot in low light environment.</li> </ol>
V1.11.00	<ol style="list-style-type: none"> <li>1. Remove the PSIA protocol, fixing the issue of getting the snapshot without authentication.</li> </ol>
V1.10.01	<ol style="list-style-type: none"> <li>1. Modified that when pre/post event image is set as 0, the device should send off one snapshot.</li> <li>2. Modified FTP time-out to 240 seconds.</li> <li>3. Fixed the issue that the device isn't deleted from mydlink after factory reset and re-connecting to Internet.</li> <li>4. Fixed the issue that failed to delete the first user info in the guest list.</li> <li>5. Fixed the issue that when SD memory size is full by recording, the e-mail notification isn't sent off.</li> <li>6. Fixed the issue that failed to SD playback on mydlink portal.</li> <li>7. Fixed the issue that the device can't rescan any SSID after changing from wireless to wired connection in some operation step.</li> <li>8. Fixed the issue that device would reboot unexpectedly when performing the endurance test.</li> <li>9. Fixed the issue that device would stop SD recording when performing the endurance test.</li> <li>10. Fixed the issue that device would stop to upload the video clips to the FTP server after performing the endurance test.</li> <li>11. Fixed the issue that live video would stop and show error message after performing the endurance test.</li> <li>12. Fixed the issue that after performing the endurance test, device would stop uploading snapshots to SMB when motion is triggered.</li> <li>13. Fixed the issue that failed to download device logs.</li> <li>14. Fixed the issue that recording indicator is turned off when motion stopped with enabled schedule recording.</li> <li>15. Fixed the issue that ePTZ patrol would be stopped unexpectedly after patrol runs for many hours.</li> <li>16. Fixed the issue that error message window would pop up when log in by new user account or switch video profile on Live Video page.</li> <li>17. Fixed the port conflict issue when configure HTTP/HTTPS/RTSP port.</li> <li>18. Fixed the wireless connection issue if wireless SSID has the special characters.</li> <li>19. Fixed the issue of FTP access problem with special character "\$" used for the first letter of account data.</li> </ol>
V1.01.18	<ol style="list-style-type: none"> <li>1. Remove the default account "guest".</li> <li>2. RTSP Authentication is default enable.</li> </ol>

**Known Issues:**

---

<b>Firmware Version</b>	<b>Known Issues</b>
V1.10.01	Spec change: G.726 audio codec wouldn't be supported in FW v1.10 or later.

**Related Documentation:**

---

N/A