Firmware Version: V2.00
Prom Code Version: N/A
Published Date: 2015/03/17

Content:

Upgrading Instructions: 2
New Features: 2
Problems Fixed: 3
Known Issues: 4
Related Documentation: 5

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2013/12/04	DNR-202L	A1
V1.01	2014/06/20	DNR-202L	A1
V1.02	2014/09/18	DNR-202L	A1
V2.00	2015/03/16	DNR-202L	A1

Upgrading Instructions:

1. Upgrade by using the Web-UI.

New Features:

Firmware Version	New Features
V1.00.22	1. New model MP firmware release.
V1.01.00	1. Update the mydlink agent to 2.0.17-b45.
V1.02.01	1. Update the mydlink agent to V2.0.18-b08. 2. Add "Universal Model" selection to allow adding unsupported cameras.
V2.00.11	1. Change the Web UI to follow the DNR-312L style. 2. Update the mydlink agent to V2.0.18-b44.

Enhancements:

Firmware Version	Problems Fixed
V1.00.22	N/A
V1.01.00	1. To add the function "Event Settings" on Landing Page. 2. Modify the live icon description.
V1.02.01	1. Add Camera support: DCS-930LB1/ DCS-932LB1/ DCS-942LB1/ DCS-6004L/ DCS-6005L.
V2.00.11	1. Disable SSL2.0/3.0/RC4/DES

Problems Fixed:

Firmware Version	Problems Fixed
V1.00.22	N/A
V1.01.00	1. Fixed DLAB Bug DBG13100305: When entering a correct account and a wrong password to register, NVR would not show any warning message and pass to the next flow. 2. Fixed DLAB Bug DBG13080170: Audio is distorted on DCS-931L, DCS-933L and DCS-5020L. 3. Fixed DLAB Bug DBG13090288: Playback could not play recording files by speeding up to 1/4/8/16/32 normally. It would stop after a while. (Tested with IE8, IE9, Firefox and Chrome) 4. Fixed DLAB Bug DBG13080155: Connecting to the NVR via IE7 for the first time fails. 5. Fixed DLAB Bug DBG13080041: Playback could not play recording files by speeding up to 1/4/8/16/32 normally. It would stop after a while. (Tested with IE8 & IE9) 6. Fixed DLAB Bug DBG13020011: Live view not displaying after enabling full screen and Auto Scan for a long time. 7. Fixed D-Track HQ20140107000013: Export avi the video and audio will not sync. 8. Fixed D-Track HQ20140113000014: NVR log shows a recording has been deleted due to disk full. However, when accessing playback the recording show up in red. If this recording is selected, it will not play. 9. Fixed D-Track HQ20140116000020: The image enhancement button is always grayed out 10. Fixed D-Track HQ20140128000008: DNR-202L playback function not working with IE11 and Firefox v26.0
V1.02.01	1. Fixed DLAB Bug DBG13020096: Converting 2 hours recording would cause the browser to crash. 2. Fixed DLAB Bug DBG13090341: Recording of all channels stops intermittently without a log entry noting this. 3. Fixed DLAB Bug DBG14050136: Translation of "OSD setting" on live video and playback page in all supported languages. 4. Fixed DLAB Bug DBG14050187: Both Safari and Firefox cannot display normally in live video mode with mydlink. 5. Fixed DLAB Bug DBG13090343: Some sentences have all bold descriptions in Spanish language. 6. Fixed DLAB Bug DBG13090314: Export files are not complete. When exporting a 1 hour video only 6 files are exported (Watermark/ Standard/ AVI file)(Tested with DCS-932 and DCS-6818 - B1). 7. Fixed DLAB Bug DBG14050133: Live video could not be watched on Opera browser. (Opera 21.0.1432.67) 8. Fixed DLAB Bug DBG13090356: Change fixed quality of DCS-3715 to "very high" but it shows "customize" on DCS-3715 UI. 9. Fixed DLAB Bug DBG14050134: Live video could not be watched on Safari browser in Mac OS. 10. Fixed DLAB Bug DBG13020075: No warning message would popup when converting a recording file without setting the cue-in and cue-out. 11. Fixed DLAB Bug DBG13020016: Firmware version on the title of page is not displayed correctly. 12. Fixed DLAB Bug DBG13020018: Time bar in PLAYBACK is not visible when using non-IE browsers. 13. Fixed DLAB Bug DBG13020019: Corrected typos in the SUPPORT page.

	14. Fixed the mydlink Bug 8232: There is no live video and playback video on Mac 10.9/ Safari 7 15. Fixed the mydlink Bug10943: Couldn't watch live view on DNR-202L after updating JAVA to ver 67
V2.00.09	1. Fixed DLAB Bug DBG14120563: Could not always update camera IP and model successfully. 2. Fixed the issue that model list can't select from the camera search page. 3. Switching the language on GUI wizard, the change is not applied immediately. 4. Fixed DLAB Bug DBG15020207: New user account can still login using the web Playback page. 5. Fixed DLAB Bug DBG15020213: Did not support Settings: Record on Motion, but shows in the help page. 6. Fixed DLAB Bug DBG14090470: After changing DCS-930LB1/932LB1 frame rate to auto, frame rate setting would be grayed out. 7. Fixed DLAB Bug DBG15020236: Internet Explorer stops working during endurance test. 8. Fixed DLAB Bug DBG15020214: Cannot modify user account privileges. 9. Fixed DLAB Bug DBG15020215: Auto Scan interval remains at 5 seconds after changing it to 3 seconds. 10. Fixed DLAB Bug DBG15020217: Whether playing back a DI recording or motion recording, initially the recording would show both the motion and DI trigger icon then only shows the motion trigger icon. 11. Fixed DLAB Bug DBG15020202: device did not automatically overwrite after the HDD is full. 12. Fixed DLAB Bug DBG15020211: Device always displays incorrect time setting after editing the schedule. 13. Fixed sending an incorrect URL to DNR-202L causes it to crash. 14. Fixed DLAB Bug DBG15020251: Device default IP would be 0.0.0.0.
V2.00.10	1. Fixed DLAB Bug DBG15020253: Wizard unable to search for cameras in the same LAN subnet as NVR, to add but Setup Wizard SE software can find cameras.
V2.00.11	1. Fixed DLAB Bug DBG15020203: The HDD LED turns off after the HDD is full, but the HDD is still mounted. 2. Fixed DLAB Bug DBG15030170: If DI triggers a camera event, the NVR only responds to event recordings and send email alerts for the first 7 minutes. 15. Fixed DLAB Bug DBG15030173: Browser UI not responding when playing Back a camera motion recording. 16. Fixed DLAB DBG15020217: Whether playing back a DI recording or motion recording, initially the recording would show both the motion and DI trigger icon then only shows the motion trigger icon. 3. Fixed DLAB DBG15030164: DUT couldn't set DCS-6112B1 motion area.

Known Issues:

Firmware Version	Known Issues
V1.00.22	N/A
V1.01.00	1. Safari browser above 6.1 will not display the video on a MAC OS.
V1.02.01	1. Export AVI function will not work on MAC OS.

V2.00.11	1. Export AVI function will not work on MAC OS. 2. Upgrade to V2.00, the device will be factory default. 3. Not supporting windows area of motion setting.

Related Documentation:

N/A