



DAP-1360 Firmware Release Note

Firmware: v2.10 (build b02)

Hardware: B1

Date: 07, July, 2010

Firmware Version: ver2.10b02

Firmware Date: 06 Jul 2010

KERNEL: Linux version 2.6.19

Realtek Turn-key SDK version: v2.3

ToolChain: rsdk-1.3.6-5181-EB-2.6.19-0.9.30_20090714

WLAN Version: Wed May 5 10:38:31 CST 2010

Checksum: 0x7695A9CA

Problems Resolved:

1. Fix firefox login issue
2. change bootloader ip to default ip.
3. Change AP with Bridge mode WPS add flow.
4. Reboot confirm message incorrect 136 -> 1360.
5. Passed WiFi Cert
6. Support smac using telnet
7. Add dhcp dns/wins/gateway
8. Show version + language
9. Support Win7 Logo
10. Fixed web server crash if using telnet to port 80
11. Update language string
12. Update check list format
13. Need to login to get chklst.txt

Enhancements:

NA

Firmware: v2.00 (build b17)

Hardware: B1

Date: 01, Feb, 2010

Firmware Version: ver2.00b17

Firmware Date: 01, Feb, 2010

Linux version 2.6.19

ToolChain: rsdk-1.3.6-5181-EB-2.6.19-0.9.30_20090714

D-Link Corporation confidential



WLAN Version: Thu Dec 24 10:39:55 CST 2009

Checksum: 0x07d7e696

Problems Resolved:

1. 1sr release.

Enhancements:

1. NA
-