



Firmware Version: 1.06rc020
Published Date: 2015/07/09

Content:

Upgrading Instructions:..... 2

 Upgrading by using Web-UI..... 2

New Features:..... 3

Changes of MIB & D-View Module:..... 3

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.02rc017	2015/02/05	DAP-2330	A1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**

The screenshot shows the D-Link DAP-2330 Web-UI interface. The top navigation bar includes Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree view with DAP-2330, Basic Settings, Advanced Settings, and Status. The main content area displays the 'System Information' page with the following details:

Model Name	DAP-2330
Firmware Version	1.06 11:41:24 07/02/2015
System Name	D-Link DAP-2330
Location	
System Time	01/04/1970 00:15:54
Up Time	3 Days, 00:15:55
Operation Mode	Access Point
MAC Address	c4:a8:1d:90:cd:90
SSID 1~7	c4:a8:1d:90:cd:91 ~ c4:a8:1d:90:cd:97
IP Address	192.168.0.201

New Features:

Support CWM v1.02

1. Disassociation supported on multi-SSID
2. Support Captive portal customization
3. Support config file upload from CWM

Changes of MIB & D-View Module:

CWM_DAP2330 v1.06-R16

Problems Fixed:

Firmware Version	Problems Fixed
V1.06	1. Fixed issue of client can't access the Internet when Ethernet to WLAN disable 2. Modify timezone. 3. Fix captive portal on other SSID(including 5G primary and MSSID) will not work when captive portal on 2.4G primary SSID is not enabled

Known Issues:

Firmware Version	Known Issues
V1.06	None

Related Documentation:

- DAP-2330 User Manual v1.03