



DAP-2610 Firmware Release Notes

Firmware: 1.01B028_RC048 BETA

Hardware: Ax

Date: March 20, 2019

Problems Resolved:

1. Fixed firmware version not matching the CWM module.
 2. IGMP Snooping stop LLMNR packets if AP does not receive IGMP Report from client.
-