



Firmware Version: V1.11

Prom Code Version:

Published Date: 2012/10/23

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2010/11/23	DCS-6511	A1
V1.11	2012/10/23	DCS-6511	A1

Upgrading Instructions:

1. Upgrading by using Web-UI

New Features:

Firmware Version	New Features
	1. Add the 4:3 & 16:9 aspect ratio switch function.
	2. Add the Number of active profiles switch function
	3. Add the Exposure Mode of image settings.
	4. Add the de-noise of image settings.
V1.11.13	5. Add NIPCA Protocol:
	6. Add IPV6, QoS, CoS, RTSP multicast, RTSP digest authentication
	7. Add ftp sub directory support
	8. Support DUSA request snapshot CGI

Problems Fixed:

Firmware	Problems Fixed
Version	
V1.11.13	 Fixed DUT would be in black screen after zoom out in LIVE VIDEO page Fixed Live Video would be unavailable after live view by Chrome for a while Fixed I.E would popup warning message when change profile to live view DUT with new user account in LIVE VIDEO page. Fixed DUT would upload invalid recording files to a SMB server Fixed There isn't any recording file in 10/8 20:00-22:00 and all recording files are only 3 KB after 10/8 23:00 Fixed the Recording Indicator still blink when SD card have been removed. Fixed the black screen instead of video on the IE9 Fix sender's interface in PPPoE mode. Fixed NTSC frame-rate Setting = 12 \ 5 / PAL Setting = 15 \ 12 \ 10 \ 7, The image is not smooth Fixed the System log records the access list error problem Fixed smart phone issue Fixed JPEG quality will be abnormal, when use the NIPCA to get the JPEG quality.
	13. Fix bug for Samba server cannot be mounted at different network segment





14. Fix Gmail test fail when change time
15. Fix sign of recording out of schedule time
16. Fixed the live video & audio sync issue.
17. Recording size change to 50MB/ 60sec and Event clip change to 5MB.
18. Fix uPnP port forwarding setting and status
19. Fix ftp can accept '\' or '/' character in path
20. Fix bug: after enable https, the HTTP server be restarted too late.
21. Fix rewrite condition changes from 80% to 90%
22. Fixed autofocus abnormal when the device reboot.
23. DUT DDNS didn't update IP and would reboot after enable DDNS.

Known Issues:

Firmware Version	Known Issues
V1.00.04	KI046 - NAS recording compatible issue for DCS-6511 Network Camera.docx

Related Documentation:

N/A

