



Firmware Version: V2.12.01
Prom Code Version:
Published Date: 2015/10/1

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	3
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.12.01	2015/10/1	DCS-930L	B1,B2
V2.11.03	2015/9/1	DCS-930L	B1,B2
V2.10.04	2015/6/29	DCS-930L	B1
V2.01.03	2015/2/6	DCS-930L	B1
V2.00b6	2014/7/2	DCS-930L	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V2.12.01	<ul style="list-style-type: none"> 1. Updated mydlink agent to 2.0.19-b54n 2. Updated Digital Signature
V2.11.03	<ul style="list-style-type: none"> 1. Update mydlink agent to 2.0.19-b54 2. Add the denoise mechanism to reduce the background noise 3. Add the login check mechanism to solve Brute Force Attack issue 4. Add Hardware Version item on the Status page of the camera's web-GUI. 5. Change the model and model number of the UPnP properties. <p>F/W V2.11.03 only supports D-ViewCam version as below or above.</p> <ul style="list-style-type: none"> 1. DCS-100 V3.6.5 + DP V1.6.13 2. DCS-100 V4.0.4 + DP V2.0.15
V2.10.04	<ul style="list-style-type: none"> 1. Update mydlink agent to v2.0.19-b35. 2. Support auto image setting switching mechanism for H/W B1 and B2 (or above) camera lens. (*H/W B2 or above only supports v2.10.04 or above)
V2.01.03	<ul style="list-style-type: none"> 1. Upgrade mydlink agent to v2.0.18-b61 2. Remove SSL, change to support TLS.
V2.00b6	Initial version. F/W v2.00 is not backward compatible to H/W Ax version.

--	--

Problems Fixed:

Firmware Version	Problems Fixed
V2.11.03	<ol style="list-style-type: none">1. Fixed the IE11 compatibility issue in Windows 10.2. Change WPS LED behavior blinking time on WPS error/timeout to 10 seconds.3. Remove the reboot function by pressing and holding the reset button in less than 3 seconds.4. Add the pop-up warning message when the user creates an existing user account on Device Web GUI.5. Support to auto-create FTP folder if the folder doesn't exist on FTP server.
V2.10.04	<ol style="list-style-type: none">1. Remove one Hidden webUI.2. Fixed HTTPS issue that causes Day/Night control not work from portal/app.3. Fixes the issue in which IP Cam cannot create FTP folder with FTP server on Netgear R7000 Router.4. Fixed CGI /reset.cgi reboot command not work issue.5. Modify Time Zone Table list to support some existing time zones changes.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A