

DIR-LX1870 Firmware Release Notes

Firmware: FW v1.01

Hardware: Rev. Ax

Problem Resolved:

- Improve 2.4G signal under very interference environment.
- Fix 2.4G auto channel issue.
- Change default wireless security to WPA2-personal
- Fixe Mesh topology display issue.
- Fixed duplicate IP issue in some situation.
- Support more encryption type of uplink connection.

Enhancements:

- Optimize app login speed when unplug WAN port.
- Optimize client list display issue.
- Optimize central image upgrade.

----- END -----