



DIR-X4860 Firmware Release Notes

Firmware: 1.02B01

Hardware Revision: A1

Date: June 18, 2020

Problems Resolved:

1. Fixed the issue that 2.4GHz clients connecting to DIR-X4860 will result in disconnection after a while.
2. Fixed 802.11kv bug.
3. Fixed when different schedules are configured, WiFi daemon is unable to restart

Enhancements:

1. Added country code – KR.
2. Made “WPA2-Personal” default security type.

Known Issues:

1. WPS 2.4G and 5G LED blinking frequency is not stable, sometimes fast sometimes slow
 2. UPnP port opened and some old cameras can't be viewed from PC via UPnP.
 3. Schedule rule is unable to be saved when setting too many blocks.
 4. Android Quick VPN failed.
 5. Router may reboot occasionally with heavy traffic running on wired and 2.4GHz simultaneously.
-