

DNS-326 QSS Release Notes

the changes of v1.0.0.24
o Bugs:
1. remove SMB.exe process
the changes of v1.0.0.23
o Wording:
1. "Create Password" page
2. "Check Network" page
o improve the timing issues (format process and map process)
Summary of changes of v1.0.0.22
o keep the samba link after PC reboot.
o Remove the ubavailable volume(network link) in QSS volume selection box
o Fixed that it might save incorrect timezone parameter in timezone setting page
o show up the target link with disconnected status
o fixed that the formatting progress bar shows incorrectly status.(sometimes)
Summary of changes from v1.0.0.16 to v1.0.0.17
o support for windows vista and win 7.
o try to request the device for information again, when QSS got a NULL packet.
o add discovery function
o change all the illustrations
o fix the incorrect partition size when user specified the "both" profile with raid1
o improve that mapping action for iscsi and samba.
o Add Dlink digital certification.
o Add identify button.
Summary of changes from v1.0.0.15 to v1.0.0.16 ====================================

D-Link Corporation confidential



Nick Yao

o Change the sentence. ("After logging in, proceed to the /SETUP/Disk Management page on the web UI for advanced disk configuration.")

Summary of changes from v1.0.0.14 to v1.0.0.15 ====================================
Nick Yao o Fix the incorrect ratio of NAS and iSCSI
Summary of changes from v1.0.0.13 to v1.0.0.14
Vee Cheng
o Change red, yellow word to dark orange
o Modify install Step 2 picture
o Modify the hand of picture
o Modify HD list style
o Modify combobox style
o Modify buttom style
o Modify buttom style
o Change background to dard style
o Fix netbios name and description cannot saved issue
o Fix iSCSI volume cannot be mounted issue
Summary of changes from v1.0.0.12 to v1.0.0.13

Vee Cheng

- o Improve network data communication for Vista
- o Fix font size for Vista
- o Rename "DNS-326" to "2-Bay ShareCenter Duo DNS-326" in welcome page.
- o Change title position in welcome page.
- o Add memory buffer to improve screen display.

D-Link Corporation confidential



Summary of changes from v1.0.0.11 to v1.0.0.12 ====================================
Vee Cheng o Change Product name in page 1 o Add smb, iSCSI mount retry function after formatting disk.
Summary of changes from v1.0.0.10 to v1.0.0.11 ===============================
Vee Cheng o Change volume mount sequence to fix mount failed issue o Change the word color (from white to blue) of Basic setting page. o Fix Easy Search and Wizard cannot co-exist. Summary of changes from v1.0.0.9 to v1.0.0.10 ===============================
Vee Cheng o Modify volume scan function to fix lag issue. o add second buffer for install animation. o change skip password fucntion, show a box to alert user the password is empty. o Volume index change from "0, 1" to "L, R". o fix format failed when timezone value is negative. o Change the word color of welcome page. Summary of changes from v1.0.0.8 to v1.0.0.9
Vee Cheng o Add skip password setting.

Summary of changes from v1.0.0.7 to v1.0.0.8 $\,$

D-Link Corporation confidential

o Add iSCSI volume selection.



Vee Cheng

o fix focus issue in hard drive setting pages

Summary of changes from v1.0.0.6 to v1.0.0.7

Vee Cheng

- o fix network command timing issue. (EZWizard sometimes cannot show the current status)
- o correct the tab order
- o fix multi-language library
- o change NAS cofiguration save time (NAS will save all configuration after basic setting)
- o Add version string on UI

Nicholas Yao

o use marco to short the code (String on UI)