



COVR-1300E Firmware Release Notes

Firmware: FW v1.01

Hardware: Rev. Ax

Data:2017/8/21

Problem Resolved:

- Modify DHCP client Bootp flags to unicast
- Fix issue when LAN networking IP address change by D-Link WiFi APP

● **Enhancements:**

----- END -----