



## **DAP-1520 Firmware Release Notes**

**Hardware: Rev. Ax**  
**Firmware: FW v1.04**  
**Date: 2014/07/01**

### **Enhancements:**

- (1) Power LED will turn into solid Orange if Signal of Uplink/root Access Point becomes weak, suggest to move the DAP-1520 to a closer place for better connection.
- (2) Enhance MacBook Compatibility.

### **Problems Resolved:**

NA

### **Known Issues:**

NA