



DAP-1520 Firmware Patch Notes

Firmware: v1.09.B01 [BETA04]

Hardware: A1

Date: 2016/08/01

Note:

None

Problems Resolved:

Fixed Security vulnerability listed below:

- Added the ability to enable/disable PIN WPS
 - Discovered by: Cedric Conti
 - Reported by: Tommi Vänninen tommi@vanninen.org
- WPS PIN is disabled by default

Enhancements:

None

Known Issues:

None

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.