



Firmware Version: V2.00
Prom Code Version:
Published Date: 2014/10/20

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	2
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2012/1/12	DCS-6112 DCS-6113	A1
V1.10	2012/2/2	DCS-6112V DCS-6113V	A1
V2.00	2014/10/20	DCS-6112 DCS-6113 DCS-6113V	B1

Upgrading Instructions:

This is first FW version for HW B1 which is not backward compatible to HW Ax version.

New Features:

Fireware Version	New Features
V1.00	N/A
V1.10	N/A
V2.00	1. Enhance frame rate to from 1920x1080@15fps to 1920x1080@30fps 2. Enhance IR illuminator distance from 10meter to 15meter

Problems Fixed:

Firmware Version	Problems Fixed
V1.00	N/A
V1.10	N/A
V2.00	1. Remove GSM-AMR UI option 2. Remove "one hour" option from NTP server setting 3. Fix IE10 UI bugs 4. Fix the Reboot schedule NIPCA cgi 5. Fix D-Lab bug DBG13110343: IPV6 DNS couldn't be shown in 2 lines when the DUT receive 2 IPv6 DNS address 6. Fix D-Lab bug DBG13120232: camera often logs critical LANDAP parse incorrect ID when DVC connect to DUT.

Known Issues:

Firmware Version	Known Issues
V1.00	N/A

V1.10	N/A
V2.00	N/A

Related Documentation:

N/A