



Firmware Version: V1.05 Prom Code Version: N/A Published Date: 2016/7/13

#### **Content:**

Upgrading Instructions:	. 2
New Features:	. 2
Problems Fixed:	. 2
Known Issues:	. 3
Related Documentation:	. 3



Revision History and System Requirement:					
<b>Firmware Version</b>	Date	Model	Hardware Version		
V1.00	2014/06/10	DCS-6315	A1		
V1.01	2014/11/10	DCS-6315	A1		
V1.02	2015/1/13	DCS-6315	A1		
V1.03	2015/10/5	DCS-6315	A1		
V1.04	2015/10/12	DCS-6315	A1		
V1.05	2016/7/13	DCS-6315	A1		

## Upgrading Instructions:

Follow the steps below to upgrade the firmware:

- 1. Download the latest firmware file to your hard drive from the D-Link website.
- 2. Log-in camera web UI and go to **Maintenance/Firmware** web page upgrade
- 3. Locate the file (upgraded firmware) on your hard drive by clicking **Choose File**.
- 4. Click **Upload** to upgrade the firmware on your camera.

#### **New Features:**

**D-Link** 

Fireware Version	New Features
V1.01.00	1. Recording file maximum size change to 50MB
	2. Support manual setting "Dynamic DNS Server"

## **Problems Fixed:**

Firmware Version	Problems Fixed
V1.01.00	<ol> <li>Improve the image in low light environment.</li> <li>Support Motion &amp; Privacy Mask setup for Non-IE Browser</li> </ol>
V1.02.00	<ol> <li>Fixed the security of SSL 3.0.</li> <li>Fixed the security of getting the snapshot without authentication</li> </ol>
V1.03.03	<ol> <li>Fixed the security issue of NTPd issue</li> <li>Fixed the security issue of tunneling RTSP streaming over HTTP</li> <li>Fixed the Cross-Site Scripting(XSS) issue</li> <li>Fixed the Cross-Site Request Forgery (CSFR) issue</li> </ol>
V1.04.00	1. Upgrade to new signing keys for fixing Code-Signing Key issue
V1.05.00	<ol> <li>Enhancement for security issue:         <ul> <li>Support TLS 1.1/1.2.</li> <li>CSRF protection default enabled and follow DHQ CSRF response rule</li> <li>Fixed CSRF and Referrer issue.</li> <li>Cross Site Scripting(XSS) issue.</li> <li>Disable SSH connection.</li> </ul> </li> </ol>

# dlinkigreen



	f. Close unknown hidden TCP port 1010.
2.	Fixed snapshot/video recording issue while browse UI in IE11.
	Fixed "Image setup" page can't be shown in Safari.
4.	Fixed Curl issue -mail server SMTP authentication fail.
	Fixed D-Track #HQ20151027000002 [DEUR20151023000013] New Mail
	Client in firmware is not RFC 2821 conform.
6.	Remove "percentage" from motion detection settings.

## **Known Issues:**

Firmware Version	Known Issues
	N/A

# **Related Documentation:**

N/A

