



Firmware Version: V1.11
Prom Code Version:
Published Date: 2017/1/18

Content:

Upgrading Instructions:.....	2
New Features:.....	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2015/9/7	DCS-6517	A1
V1.01	2015/10/20	DCS-6517	A1
V1.10	2016/1/13	DCS-6517	A1
V 1.11	2017/1/18	DCS-6517	A2

Upgrading Instructions:

Please follow normal business camera FW upgrade procedure.

New Features:

Fireware Version	New Features
V1.00	First release

Problems Fixed:

Firmware Version	Problems Fixed
V1.00	N/A
V1.01	Change new digital signature 2015
V1.10	<ol style="list-style-type: none"> 1. Fix Web page can't fully display after reset, reboot or test FTP function. 2. Modify RTSP authentication default from disable to the Basic.
V 1.11	<ol style="list-style-type: none"> 1. RTSP authentication type couldn't be settled in basic 2. RTSP authentication type couldn't be settled in disable 3. Home icon of the PTZ panel would be malfunction 4. Contents of snapshots that triggered by the same event would be different in the e-mail and FTP server 5. SSL upgrade to 1.0.2j 6. SHA-2 encryption 7. ONVIF 16.01 8. Close all telnet or SSH..etc backdoor

Known Issues:

Firmware Version	Known Issues
V1.00	<ol style="list-style-type: none">1. Camera would reboot unexpectedly after remove the SD card during SD card recording is processing. The workaround solution is, do not remove SD card when the recording is writing. The issue will be fixed in next FW version.2. When camera upload configured file, the schedule recording setting of SD card is not proceed normal. The workaround solution is, reboot the camera to recover. The issue will be fixed in next FW version.
V1.10	<ol style="list-style-type: none">1. DUT would reboot unexpectedly after remove the SD card during SD recording. It's Hardware limitation for system protection.

Related Documentation:

N/A