



Firmware Version: V2.01
Prom Code Version: N/A
Published Date: 2017/11/14

Content:

Upgrading Instructions:.....	2
New Features:.....	2
Problems Fixed:	2
Known Issues:	Error! Bookmark not defined.
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2012/10/25	DCS-7513	A1
V1.01	2013/06/13	DCS-7513	A1
V1.10	2015/01/05	DCS-7513	A1
V1.11	2015/09/18	DCS-7513	A1
V1.12	2015/10/12	DCS-7513	A1
V2.00	2017/1/9	DCS-7513	B1
V2.01	2017/11/14	DCS-7513	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in ".pkg" file format.
2. Log-in camera web UI and enter Setup/Advanced Setup/System configuration/Firmware upgrade
3. Click Browse... and specify the firmware file.
4. Click Upload. The camera starts to upgrade and will reboot automatically when the upgrade completes.
5. FW v2.00 doesn't backward compatible with HW ver. A, it's only applied for HW ver. B

New Features:

Fireware Version	New Features
V1.01.03	1. Add SNMP function
V2.00	1. New GUI design 2. Support face detection 3. Frame rate up to 60fps

Problems Fixed:

Firmware Version	Problems Fixed
V1.01.03	1. Remove the "guest" account. 2. RTSP Authentication change to default enable 3. Fixed the UPNP security issue.
V1.10.00	1. Fixed the security of SSL 3.0. 2. Fixed the security of getting the snapshot without authentication

V1.11.11	<ol style="list-style-type: none"> 1.Fixed the security issue of NTPd issue 2.Fixed the security issue of tunneling RTSP streaming over HTTP 3.Fixed the Cross-Site Scripting(XSS) issue 4.Fixed theCross-Site Request Forgery (CSFR) issue 5.Image improvement
V1.12.00	<ol style="list-style-type: none"> 1. Upgrade to new signing keys for fixing Code-Signing Key issue
V2.01.00	<p>Enhancement:</p> <ol style="list-style-type: none"> 1. Add "Stream authentication" on HTTP setting page. <p>Security issue:</p> <ol style="list-style-type: none"> 1. Update to jquery 1.12.0 2. RTSP hard-coded credentials security hole [DBG16110359] <p>D-Lab bug fixed:</p> <ol style="list-style-type: none"> 1. Improved image quality in 6500k. 2. Fixed Chrome, Safari & Firefox compatible issue. 3. D-ViewCam Compatible issue.[DBG16080140, 141,142, 144, DBG17070341, 342] 4. Issue of snapshot sent by email. [DBG16080206, 207] 5. The photo wasn't correct saveing after take a snapshot.[DBG17080735] 6. Max. Frame rate settings issue [DBG17090327, 329] 7. Minor bugs fixed.

Firmware Version	Known Issues
	N/A

Related Documentation:

N/A