



**Firmware Version:** V2.02.01 **Published Date:** 2020/09/04

#### **Content:**

| Revision History:       | 2 |
|-------------------------|---|
| Upgrading Instructions: | 2 |
| New Features:           | 2 |
| Enhancements:           | 2 |
| Problems Fixed:         | 3 |
| Known Issues:           | 3 |
| Related Documentation:  | 3 |





**Revision History and System Requirement:** 

| <b>Firmware Version</b> | Date       | Model    | Hardware Version |
|-------------------------|------------|----------|------------------|
| V2.02.01                | 2020/09/04 | DCS-7517 | B1               |
| V2.01.00                | 2019/1/25  | DCS-7517 | B1               |
| V 2.00.03               | 2017/7/27  | DCS-7517 | B1               |

## **Upgrading Instructions:**

Follow the steps below to upgrade the firmware:

- 1. Download the latest firmware file from the D-Link website. The file is in ".pkg" file format.
- 2. Log-in camera web UI and enter **Setup/Advanced Setup/System**

### configuration/Firmware upgrade

- 3. Click Browse... and specify the firmware file.
- 4. Click Upload. The camera starts to upgrade and will reboot automatically when the upgrade completes.
- 5. FW v2.00 doesn't backward compatible with HW ver. A, it's only applied for HW ver. B

Notice: HW B1 is applied with different platform, the FW can't not be backward compatible with HW A1.

#### **New Features:**

| Fireware Version | New Features  |
|------------------|---|
| V2.01.00         | 1. Add CGI for MCD project                                  |
|                  | 2. Set disable for "http stream authentication" as default. |
|                  | 3. Upgrade jQuery 1.12.0                                    |
|                  | 4. Update new digital sign.                                 |
| V2.00.03         | 1. New HW platform  |
|                  | 2. New GUI design   |
|                  | 3. Frame rate up to 30fps for 5 megapixels                  |

#### **Enhancements:**

| Firmware Version | Enhancements           |
|------------------|------------------------|
| V2.02.01         | 1. TLS 1.2<br>2. SHA 2 |

## **Problems Fixed:**

| Firmware Version | Problems Fixed  |
|------------------|---|
| V2 02 04         | 1. Remove ""www.dlinkddns.com"" 2. Time Sync. (2019>2037)   |
| V2.02.01         | <ul><li>3. Synchronize the permissions of camera users and ONVIF users to solve the problem that the user account cannot obtain images</li><li>4. Wrong time digital signature of ActiveX</li></ul> |





# **DCS-7517 Firmware Release Notes**

|          | 5. Multicast group address could be set out of 224.0.0.0 to 239.255.255.255  |
|----------|--|
| V2.01.00 | <ol> <li>Change new digital sign</li> <li>Bug fixed:         <ul> <li>a. Remove resolution 720x576 which doesn't list on datasheet.</li> <li>b. Add copyright and digital sign on video plug-in software.</li> <li>c. Fixed video uploaded issue to NAS by tamper detection trigger.</li> <li>d. Fixed the wrong information on DI/DO status.</li> <li>e. Minor bugs fixed.</li> </ul> </li> </ol> |

## **Known Issues:**

| Firmware Version | Known Issues   |
|------------------|--|
| V2.01.00         | 1. DBG18090224: Due to the compatibility issue between panoviewer and non-IE browser, after the event is triggered, the alarm light response on the live view is sometimes delays and cannot be fully synchronized.          |
| V2.01.00         | 2. DBG18090307: Due to the compatibility issue between panoviewer and non-IE browser, after switching profiles on the live view page, the display of real-time images is sometimes delayed and cannot be fully synchronized. |

# **Related Documentation:**

N/A

