



Firmware Version: v1.02.09

Prom Code Version:

Published Date: 2015/6/16

Content:

grading Instructions: Error! Bookmark not defi	
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
v1.02.09	2015/6/16	DCS-850L	A1
v1.01.06	2015/3/16	DCS-850L	A1
v1.00b7	2014/10/30	DCS-850L	A1

New Features:

Firmware Version	New Features
	1. Update mydlink Agent to v2.0.19-b35
v1.02.09	2. Remove Bonjour _http service, and add Bonjour _dcamera service
	3. Support CGI command of auto-pan stop
v1.01.06	1. Upgrade mydlink agent to v2.0.18-b61
	2. Remove SSL, change to support TLS.
v1.00b7	1 st version

Problems Fixed:

Firmware Version	Problems Fixed
	Fixed HTTPS issue that cause Pan/Tilt and Day/Night control not work from portal/app
v1.02.09	 Modify Time Zone Table list to support some existing time zones changes. Fixed when IP Cam connects to wireless router and its Direct Mode is also activated simultaneously, the wireless devices can discover other IP cameras (connect to wireless router) through the AP mode connection. Fixed IP Cam can not connect to a Wireless Network with a Hidden SSID.
	5. Fixed CGI /reset.cgi reboot command not work issue







Kn	own	Issu	les:
		1334	LJ.

Firmware Version	Known Issues

Related Documentation:

N/A

Upgrading Instructions:

This camera update process is automatically done using the mydlink $^{\text{\tiny TM}}$ Baby Camera Monitor App. A firmware upgrade message will appear on the app when new firmware is available.

