



## **DIR-3060 Firmware Hotfix Release Notes**

**Firmware: 1.11B04 Hotfix**

**Hardware Revision: Ax**

**Date: March 8, 2021**

### **Overview:**

The D-Link DIR-3060 is affected by a post-authentication command injection vulnerability.

### **Problems Resolved:**

- Command Injection Web Interface (Post-Authentication)

### **3<sup>rd</sup> Party Report:**

- Takeshi Shiomitsu <takeshi at iot-inspector dot com>

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.