



## **DIR-600M Firmware Patch Notes**

**Driver: v3.06TCB01**

**Hardware: Cx**

**Date: December 12, 2017**

### **Note:**

The following only affects D-Link Models and revisions that are distributed outside the US.

### **Problems Fixed:**

D-Link was recently made aware of an issue involving leaked WPAD (Web Proxy Auto-Discovery) queries that could result in domain name collisions with our routers' DHCP default setting domain name.

Attackers may register the leaked domain and exploit the leaked queries by configuring users' IE browser proxies.

It is important to update your devices with the appropriate patch otherwise it could be potentially at risk: DIR-600M/C1, DIR-612/B1, DIR-615/T1 & T3, and DSL-2750U/I1.

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.