

DIR-882 Firmware Release Notes

Firmware: v1.10B02

Hardware: Rev Ax

Release Date: March 27, 2018

Note:

1. The firmware version is advanced to v1.10
2. The firmware v1.10 must be upgraded from the transitional version of firmware v1.04 (transitional version).

Problems Resolved:

1. Update WPA2 security patch (KRACK)
2. Upgrade dnsmasq to 2.78

Enhancements

1. Supports D-Link Wi-Fi App
(QRS mobile won't be supported from firmware version v1.10 or later version)
 2. Support image with encryption
 3. Support EU VLAN @ EU country code
 4. Support VLAN profile @ SG country code
-