

# DIR-882 Release Note

## Firmware:

**DIR\_882\_FW120B06.BIN (WEB GUI upgrade)**

**DIR\_882\_FW120B06\_uncrypted.BIN (RecoverMode upgrade)**

**Hardware: A1 (MTK7621+MT7615N\*2)**

**Date: 2019/05/16**

**Svn : r97458**

**Author: ZengQingHuang.**

- 1. Fixed the problem that SG CountryCode Code Setting Operator's Preservation is not effective
- 2. Fixed the problem that EU VLAN of IPTV and VOIP Interfaces cannot be set to bridge mode.
- 3. The latest SKU tables incorporating Indian country code

## 发布包文件说明

文件类型	WEBGUI 升级文件
文件名	<b>DIR_882_FW120B06.BIN</b>
MD5	89a80526d68842531fe29170cbd596c3
文件类型	RecoverMode 升级文件
文件名	<b>DIR_882_FW120B06_uncrypted.BIN</b>
MD5	bf0ca8ea754ba873b1704bbcb4c179bd
其它说明：	

**DIR\_882\_FW120B05.BIN (WEB GUI upgrade)**

**DIR\_882\_FW120B05\_uncrypted.BIN (RecoverMode upgrade)**

**Hardware: A1 (MTK7621+MT7615N\*2)**

**Date: 2019/05/14**

**Svn : r97412**

**Author: ZengQingHuang.**

- 1. WEB GUI is updated to SVN1449.
- 2. Support the Vlan function of China Telecom.

- 3. Solve the problem that the long lease period of DHCPv6 server on d-track device leads to abnormal radvd process and the client can't get the IPv6 address
- 4. Solve a quickvpn problem raised by D-trace. When SPI is turned on, the quickvpn dialing of IOS mobile phone fails.
- 5. Remove device startup and send igmpv2 message to solve the problem of IPTV playback in Singapore
- 6. Modify the channel list corresponding to the IN country code according to the document <PSD-001-01009\_D-Link Wi-Fi frequency table\_20190102.pdf>
- 7. Resolve the problem of IPTV stop broadcasting after 5 minutes in Vietnam.

### 发布包文件说明

文件类型	<b>WEBGUI 升级文件</b>
文件名	<b>DIR_882_FW120B05.BIN</b>
MD5	55a4c6a5bbb8ca8f4ff0911c666b9bd0
文件类型	<b>RecoverMode 升级文件</b>
文件名	<b>DIR_882_FW120B05_uncrypted.BIN</b>
MD5	f50969f9562cdff6658570fa30bfa211
其它说明：	

**DIR\_882\_FW120B01.BIN (WEB GUI upgrade)**  
**DIR\_882\_FW120B01\_uncrypted.BIN (RecoverMode upgrade)**

**Hardware: A1 (MTK7621+MT7615N\*2)**

**Date: 2018/12/01**

**Svn : r95408**

**Author: ZengQingHuang.**

- 1. WEB GUI is updated to SVN1196.
- 2. Support the Vlan function of China Telecom.
- 3. Support for new spec functionality

### 发布包文件说明

文件类型	<b>WEBGUI 升级文件</b>
------	--------------------

文件名	<b>DIR_882_FW120B01.BIN</b>
MD5	99b21034f4bb5929cb6576ba1ff42368
文件类型	<b>RecoverMode</b> 升级文件
文件名	<b>DIR_882_FW120B01_uncrypted.BIN</b>
MD5	984009f6d69dd6ab0e5f728905eccbb2
其它说明：	