DIR-815 Firmware Release Notes

Firmware: FW2.03.B02
Hardware: REV. B
Date: 2013/11/17

Note:
None

Problems Resolved:

Fixed bug:

- Solved the command injection issue in 192.168.0.1/service.cgi.
- Reduced the logout timeout from ten to three minutes.
- Solved the security issue by turning off the widget function and removing the relative files like router_info.xml.
- Solved the information leakage issue inversion.php.
- Solved the security problem that the router will turn off telnet daemon when it is not in factory default mode.
- Solved the command injection issue by removing command.php.

Enhancements:
None

Known Issues:
None