DIR-860L Firmware Patch Notes

Firmware: 2.04B04_ic5b_BETA
Hardware: Bx
Date: January 4, 2019

Overview:
In November 2018, D-Link became aware of a 3rd Party security researcher that accused the DIR-860L Hardware Rev. Bx and DIR-818LW Series Hardware Revision Ax consumer routers of a remote command injection vulnerability.

After an investigation, this vulnerability is only accessible via the local-network (LAN-side) of the router and not directly from the Internet (WAN-side) since it requires access to the web browser configuration of the router.

3rd Party Report:
MinGeun Kim (pr0v3rbs _at_ kaist.ac.kr)

https://github.com/pr0v3rbs/CVE/tree/master/CVE-2018-20114

Problems Resolved:

CVE-2018-20114 - Unauthenticated OS Command Injection

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.