DAP-1860 Firmware Release Notes

Firmware: 1.04B03 Hotfix
Hardware: A1
Date: November 8, 2019

Problems Resolved:
1. Unauthenticated Command Bypass
2. HNAP Command Injection

Reported by: Nguyen Van Chung
Report Date: 10/09/2019

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.