DIR-822 Firmware Release Notes

Firmware: FW v3.11

Hardware: Rev. Cx

Data:2019/1/1

Note:

- The firmware version is advanced to v3.11.
- The firmware v3.11 must be upgraded from the transitional version of firmware v303WWb04_middle.

Problem Resolved:

- N/A

Enhancements:

- Add the TH country code for Thailand.

---------------------- END ----------------------