Firmware Version: V2.1.0

Published Date: 2016/08/26

Content:

Upgrading Instructions: 2
New Features: 2
Problems Fixed: 3
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.0.0	2015/12/01	DNR-322L	B1
V2.0.1	2016/01/21	DNR-322L	B1
V2.1.0	2016/08/26	DNR-322L	B1

Upgrading Instructions:

1. N/A

New Features:

Fireware Version	New Features
V2.0.0	1. New model MP NVR Search Utility(Mac) release
V2.0.1	N/A
V2.1.0	N/A

Enhancements:

Firmware Version	Problems Fixed
V2.0.0	N/A
V2.0.1	N/A
V2.1.0	N/A

Problems Fixed:

Firmware Version	Problems Fixed
V2.0.0	N/A
V2.0.1	1. Fixed D-Lab Bug ID: DBG15120359—Whether DHCP Enable or disable configuration , the setting time will countdown to remain 1 second and search utility stop working.
V2.1.0	1. Fixed D-Lab Bug ID: DBG16010194-- User executes NVR search utility while there are 2 NVR in the LAN and search utility works. Unplugging network cable of 2 NVR and

	clicking refresh button on the NVR search utility, NVR search utility show "Check network Failed" and cannot click close button. NVR stop working.

Known Issues:

Firmware Version	Known Issues
V2.0.0	N/A
V2.0.1	N/A
V2.1.0	N/A

Related Documentation:

N/A