



Firmware Version: V1.01_b2
Prom Code Version:
Published Date: 2013/5/28

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.01_b2	2013/5/28	DCS-5010L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.01_b2	<ol style="list-style-type: none">1. Update mydlink agent to v2.0.17-b06.2. Update h.264 Activex to v1.0.0.12.3. Only allow 0-9, a-z, A-Z, ".", "-", "_" as the user account name.

Problems Fixed:

Firmware Version	Problems Fixed
V1.01_b2	<ol style="list-style-type: none">1. Fix the problem that mydlink Agent will run twice when the camera is connecting to DIR-850L using WPS Push button.2. Fixed OSD color issue3. Fixed the direction of P/T control panel incorrect issue when Flip/Mirror enabled

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A