



**Firmware Version:** V1.03.01  
**Prom Code Version:**  
**Published Date:** 2015/10/1

---

**Content:**

Upgrading Instructions:..... 2  
New Features:..... 2  
Problems Fixed: ..... 3  
Known Issues: ..... 3  
Related Documentation: ..... 3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.03.01	2015/10/1	DCS-934L	A1,A2
V1.02.05	2015/9/2	DCS-934L	A1,A2
V1.01.03	2015/2/6	DCS-934L	A1
V1.00_b2	2014/12/9	DCS-934L	A1

## Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

## New Features:

Firmware Version	New Features
V1.03.01	<ol style="list-style-type: none"> <li>1. Updated mydlink agent to 2.0.19-b54n</li> <li>2. Updated Digital Signature</li> </ol>
V1.02.05	<ol style="list-style-type: none"> <li>1. Update mydlink agent to 2.0.19-b54</li> <li>2. Add the denoise mechanism to reduce the background noise</li> <li>3. Add the login check mechanism to solve Brute Force Attack issue</li> <li>4. Add Hardware Version item on the Status page of the camera's web-GUI.</li> <li>5. Support auto image setting switching mechanism for H/W A1 and A2 (or above) camera lens. (*H/W A2 or above only supports v1.02.05 or above)</li> <li>6. Change the model and model number of the UPnP properties.  <a href="#">F/W V1.02.05 only supports D-ViewCam version as below or above.</a> <ol style="list-style-type: none"> <li>1. <a href="#">DCS-100 V3.6.5 + DP V1.6.13</a></li> <li>2. <a href="#">DCS-100 V4.0.4 + DP V2.0.15</a></li> </ol> </li> </ol>
V1.01.03	<ol style="list-style-type: none"> <li>1. Upgrade mydlink agent to v2.0.18-b61</li> <li>2. Remove SSL, change to support TLS.</li> </ol>
V1.00_b2	1 <sup>st</sup> version

## Problems Fixed:

Firmware Version	Problems Fixed
V1.02.05	<ol style="list-style-type: none"> <li>1. Fixed the IE11 compatibility issue in Windows 10.</li> <li>2. Change WPS LED behavior blinking time on WPS error/timeout to 10 seconds.</li> <li>3. Remove the reboot function by pressing and holding the reset button in less than 3 seconds.</li> <li>4. Add the pop-up warning message when the user creates an existing user account on Device Web GUI.</li> <li>5. Support to auto-create FTP folder if the folder doesn't exist on FTP server.</li> </ol>

## Known Issues:

Firmware Version	Known Issues

## Related Documentation:

N/A