



DAP-1320 Software Release Notes

Firmware: 3.01B10

Hardware: Cx

Date: 27th, Dec, 2016

Problems Resolved:

1. Fixed it was possible to fail on connecting hidden SSID.
2. Fixed it was possible to fail on extending WEP open security type uplink AP.
3. Minor fixes of reported issues.

Enhancements:

1. Improve stabilities of uplink Wi-Fi SSID scan.

Known Issues:

None.
