



**Firmware Version:** V1.05.02  
**Prom Code Version:**  
**Published Date:** 2015/3/6

---

**Content:**

Upgrading Instructions:..... 2  
New Features:..... 2  
Problems Fixed: ..... 3  
Known Issues: ..... 3  
Related Documentation: ..... 3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.05.02	2015/3/6	DCS-2310L	A1, A2
V1.04.00	2014/12/23	DCS-2310L	A1, A2
V1.03.08	2014/6/26	DCS-2310L	A1, A2
V1.02.00	2013/7/29	DCS-2310L	A1
V1.01.10	2013/6/18	DCS-2310L	A1

## Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

## New Features:

Firmware Version	New Features
V1.05.02	1. Update the mydlink agent to 2.0.19-b02
V1.04.00	1. Update the mydlink agent to 2.0.18-b54 2. Disable the SSL2.0/3.0 3. Disable the RC4/DES
V1.03.08	1. Update the mydlink agent to 2.0.17-b76 2. Support MP4 recording format 3. Added Schedule Reboot function
V1.02.00	1. Update the mydlink agent to 2.0.17-b18 2. Support 2-way audio function at portal and APP 3. Support onvif test tool V12.06 4. Enhancements the low light image.
V1.01.10	<b>The Firmware is only supported by wizard v1.04.03 or above.</b> 1. Upgrade to UPnP v1.6.18. 2. Remove the default account "guest" 3. RTSP Authentication is default enable.

## Problems Fixed:

Firmware Version	Problems Fixed
V1.05.02	<ol style="list-style-type: none"> <li>Fixed the 2-way audio failed issue on iOS8</li> <li>Fixed the issue of faulty auto-firmware upgrade mechanism</li> </ol>
V1.04.00	<ol style="list-style-type: none"> <li>Remove the PSIA protocol. Fixing getting the snapshot without authentication.</li> </ol>
V1.03.08	<ol style="list-style-type: none"> <li>Fixed the issue of ICR switch failed in schedule mode after device reboot.</li> <li>Modified that when pre/post event image is set as 0, the device should send off one snapshot.</li> <li>Modified FTP time-out to 240 seconds.</li> <li>Fixed the issue that the device isn't deleted from mydlink after factory reset and re-connecting to Internet.</li> <li>Fixed the issue that failed to delete the first user info in the guest list.</li> <li>Fixed the issue that when SD memory size is full by recording, the e-mail notification isn't sent off.</li> <li>Fixed the issue that mydlink account is cleared out after downgrading to the previous FW version.</li> <li>Fixed the issue that camera IP doesn't update to DDNS.</li> <li>Modified the event setup that needs to create 2 media for 2 events.</li> <li>Fixed the issue of FTP access problem with special character "\$" used for the first letter of account data.</li> </ol>
V1.02.00	<ol style="list-style-type: none"> <li>Fixed the IPV6 Enable and change the http port the web server will crash.</li> </ol>
V1.01.10	<ol style="list-style-type: none"> <li>Remove the default account "guest".</li> <li>RTSP Authentication is default enable.</li> </ol>

## Known Issues:

Firmware Version	Known Issues
V1.03.08	Spec change: G.726 audio codec wouldn't be supported in FW v1.03 or later.

## Related Documentation:

N/A