

DIR-822 Firmware Release Notes

Firmware: FW v3.10B06

Hardware: Rev. Cx

Data:2018/8/17

Note:

- The firmware version is advanced to v3.10B06.
- The firmware v3.10 must be upgraded from the transitional version of firmware v303WWb04_middle.

Problem Resolved:

- N/A

Enhancements:

- Firmware image protection
- Update dnsmasq to 2.78
- Supports VLAN profile.

----- END -----
