Problems Resolved:

Project Name: DAP-1955

===

HW version: A2

Firmware Version: ver1.02b01

===

Fixed Bugs:

1. GUI Issue - After reset, DAP1955 config will return to A1