Firmware Version: V2.13.03
Prom Code Version:
Published Date: 2016/9/9

Content:

Upgrading Instructions: 2
New Features: 3
Problems Fixed: 4
Known Issues: 5
Related Documentation: 5

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.13.03	2016/9/9	DCS-2132L	B
V2.12.01	2015/12/8	DCS-2132L	B
V2.11.00	2015/10/1	DCS-2132L	B
V2.10.11	2015/8/17	DCS-2132L	B
V2.02.05	2015/1/15	DCS-2132L	B1
V2.01.06	2014/5/23	DCS-2132L	B1
V2.00.05	2014/2/17	DCS-2132L	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:
1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse… and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V2.13.03	1. mydlink agent upgrade to 2.2.0-b02. 2. Added UID support 3. Updates to adhere to latest EN300 328 requirements 4. Add support Dlink new anti-brute force mechanism(block only IP, reset when successful login from one IP) 5. Updated support URL
V2.12.01	1. mydlink agent upgrade to 2.0.19-b84. 2. Add the Chrome Bowser notify message. 3. Support TLS v1.1/1.2 and updated openSSL version to v1.01P. 4. Allowed showing 100 items in SD card single page
V2.11.00	1. Updated agent to 2.0.19b51n 2. Updated Digital Signature
V2.10.11	1. Update agent to 2.0.19b51
V2.02.05	1. Update agent to 2.0.18b09 2. Disabled SSL 3.0, RC4/DES to fix security hole 3. Added language autodetection 4. Add support for Motion detection, direct MJPEG decoding, and Privacy masks on non-IE browsers 5. Add 50MB/30 sec Event on SD function 6. Add 720P resolution for profile 2 7. Add Bonjour Name function 8. Enhance the Wi-Fi stability 9. Added new DDNS selection.
V2.01.06	1. Change Agent version to 2.0.17-b59. 2. Support 2-way audio on App 3. Support playback on App 4. Set passive mode enable of FTP as default
V2.00.05	1. 1st version for new H/W solution, B1 version

Problems Fixed:

Firmware Version	Problems Fixed
V2.13.03	1. Fixed SD card non-recording and no recording icon issues 2. Fixed PPPoE issues. 3. Fixed issue where settings were not available when accessing device through portal Advanced Mode in Firefox and Chrome 4. Fixed E-mail Header/notification issues 5. updated openssl libraries to latest to fix security issues CVE-2016-2107, CVE-2016-2105, CVE-2016-2106, CVE-2016-2109, CVE-2016-2176 6. Added input validation in certain methods. 7. Fixed "Test FTP" and "Test Email" Button Errors 8. Fixed Login issue with customized User/Password 9. Fixed issues with UPnP AV function 10. Fixed issues caused by loading configuration from early firmware releases 11. Fixed issue where device could not go to preset in the Live Video context
V2.12.01	1. Enhanced the Cross-Site Request Forgery handling including Modify CSRF protection - 403 Forbidden 2. Fixed IE11 Live page cannot click recording and snapshot function issue for Win8.1 or higher version issue. 3. Fixed mydlink can't receive sound detection mail. 4. Fixed Recording Windows Samba video drop frame issue. 5. Fixed Curl-SMTP - mail server SMTP authentication fail. 6. Fixed Curl-SMTP - the "new mail client" in all cameras with "event management" is not RFC2821 conform issue. 7. Fixed Curl-SMTP - Mail/SAMBA password bug in test mode fail. 8. Fixed mydlink bug - SD card of the re-write function value cannot be save, when enable portal schedule record. 9. Modify disable motion detection when changed IRLED or ICR setting. 10. Modify the IR Light default at maximum level. 11. Fixed Reconnect to router issue by Disable Direct Mode
V2.10.11	1. Fixed the Cross-Site Scripting(XSS) issue 2. Fixed the security issue of tunneling RTSP streaming over HTTP 3. Disable SSH connection
V2.02.05	1. Remove the PSIA protocol which allowed getting the snapshot without authentication. 2. Fixed the issue that the certificate on the camera wouldn't be reset after factory reset. 3. Fixed the issue that after performing the endurance test, camera would stop uploading snapshots to SMB when periodic trigger is set. 4. Fixed the issue of image with green tone in some case. 5. Fixed the issue of access permission configured on Access List. 6. Revised Helpful Hints for clarity.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A