DCS-5020L Firmware Patch Notes

Firmware: v1.15.01 BETA
Hardware: Ax
Date: April 27, 2018

Note:
Discovered: 1/22/2017 - Tim Carrington (carrington123_at_hotmail_co_uk)

Problems Resolved:

CVE-2017-17020 - Authenticated RCE vulnerability

Affected Models:

DCS-5009	H/W Revision Ax	FW 1.08.11 and before	Under Development
DCS-5010	H/W Revision Ax	FW 1.14.09 and before	Under Development
DCS-5020	H/W Revision Ax	FW 1.14.09 and before	Fixed 1.15.01

Security patch for your D-Link Devices

This firmware is an update security vulnerabilities in affected D-Link devices. We are releasing it as a BETA at this time, and will update with a firmware that has passed our long-term quality assurance testing at a later time. D-Link will update this continually and we strongly recommend all users to install this relevant updates.

As there are different hardware revisions on our products, please check this on your device before downloading the correct corresponding firmware update. The hardware revision information can usually be found on the product label on the underside of the product next to the serial number. Alternatively, they can also be found on the device web configuration.