Firmware Version: V1.20
Prom Code Version:
Published Date: 2012/10/09

Content:

Upgrading Instructions:..... **Error! Bookmark not defined.**
New Features:..... 2
Problems Fixed: 2
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.10	2011/12/05	DCS-6112V DCS-6113V	A1
V1.20	2012/10/03	DCS-6112V DCS-6113V	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:
1. Download the latest firmware file from the D-Link website. The file is in .rar file format.
2. Decompress the .rar file, there are three files included, two .pkg files and one .txt file.
3. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
4. Click Browse… and specify the firmware file "DCS-6112X_6113X_A1_FW_V1.20_preset.pkg".
5. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.
6. Execute upgrade process again and specify the firmware file "DCS-6112X_6113X_A1_FW_V1.20.pkg"
7. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

Note: Once user upgrade FW from v1.00 (or v1.10) to v1.20, it's unnecessary to execute "DCS-6112X_6113X_A1_FW_V1.20_preset.pkg" for advanced FW in the feature, such as v1.30. The "xxx_preset.pkg" is applied for v1.00 and v1.10 only to re-manage internal memory utilization.

New Features:

Firmware Version	New Features
V1.10	1. Support both SSL and TLS 2. Support PPPoE CHAP
V1.20	1. Support ONVIF v1.02.4 2. Support NIPCA motion detection

Problems Fixed:

Firmware Version	Problems Fixed
V1.10	1. DUT couldn't send an E-mail via Gmail (Bug ID: DBG11080235) 2. Camera hang up issue when linked by D-ViewCam (Big ID: DBG11070124 & HQ20111003000012)
V1.20	1. DBG12070079: An error message would popup and the video settings couldn't be changed. 2. DBG11100155: After firmware upgrade the logo graph settings would disappear. 3. DBG11120366: When DUT HTTP port change to 8081, add DUT by auto search would show can't connect to IP camera. 4. DBG11120227//DBG11110318: The copy button in HTML Code Examples page didn't work.

Known Issues:

Firmware Version	Known Issues
V1.10	N/A
V1.20	N/A

Related Documentation:

N/A