Firmware Version: V2.01.00
Prom Code Version:
Published Date: 2016/01/19

Content:

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2013/7/01	DCS-6915	A1
V1.10	2014/12/01	DCS-6915	A1 & A2
V2.00	2015/2/11	DCS-6915	B1 & B2
V2.00.05	2015/10/28	DCS-6915	B1 & B2
V2.01.00	2016/1/19	DCS-6915	B1 & B2

Upgrading Instructions:

Follow the steps below to upgrade the firmware:
1. Download the latest firmware file from the D-Link website.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
4. Click Browse latest firmware
5. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features
V1.00	First firmware version
V1.10	IPv6
V2.00	1. Support ONVIF Profile S, test tool v14.06 2. Support camera moves to preset point by DI trigger

Problems Fixed:

Firmware Version	Problems Fixed
V1.10	1. DBG14060563: Default of RTSP authentication changed to "Digest" 2. DBG14070022: Camera can be found after establish PPPoE by SetupWizard. 3. DBG14070043: Fix Day and night setting issue 4. HQ20140605000020: Fix the camera to be changed BW model unexpectedly. 5. HQ20140529000007: Fix the camera to go to unknown preset point occasionally. 6. HQ20140703000002: Fix the camera to rotate unexpectedly when the tilt angle is 90 degrees.
V2.00	1. DBG14090063: Fix the bug that could not set HTTP protocol successfully 2. DBG14090061: Fix the bug that wrong setting will be shown when clicking client page after setting protocol type and save in IE9
V2.00.05	1. Change new digital signature 2015
V2.01.00	1. Support MAC Address Range changed

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A