Firmware Version: V1.02.06
Prom Code Version:
Published Date: 2015/2/12

Content:

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00_b10	2014/6/16	DCS-700L	A1
V1.01_b3	2014/7/31	DCS-700L	A1
V1.02.06	2015/2/12	DCS-700L	A1

New Features:

Firmware Version	New Features
V1.00_b10	First formal release of DCS-700L firmware
V1.01_b3	1. Update mydlink agent to v2.0.17-b86 2. Add hardware version parameter for device info inquiry
V1.02.06	1. Update mydlink agent to v2.0.18-b61 2. Remove SSL and support TLS

Problems Fixed:

Firmware Version	Problems Fixed
V1.01_b3	1. Fixed the issue of some special characters (including space) displaying on Wi-Fi network list 2. Fixed the two-way audio issue that camera doesn't mute when talk function is enabled
V1.02.06	1. Fixed issue where device would not respond properly to portal commands under relay mode. 2. Fixed issue occurring randomly that could not live view on portal under relay mode.

Known Issues:

Firmware Version	Known Issues

	3

Related Documentation:

N/A

Upgrading Instructions:

The notification of FW upgrade will be automatically delivered on mydlink portal and mydlink Baby Camera Monitor app when there is a new FW release. The camera will start upgrading to the new FW after users confirm to update.