Firmware Version: V1.02.04
Prom Code Version:
Published Date: 2018/3/8

Content:

dlink green

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.02.04	2018/03/08	DCS-8000LH	A1
V1.01.01	2017/10/18	DCS-8000LH	A1
V1.00.05	2017/7/14	DCS-8000LH	A1

Upgrading Instructions:

NA

New Features:

Fireware Version	New Features
V1.02.04	Update mydlink agent to v2.2.0-b16
V1.01.01	Update mydlink agent to v2.1.0-b89
V1.00.05	Initial Release

Problems Fixed:

Firmware Version	Problems Fixed
V1.02.04	1. Fix WPA2 key reinstallation attacks issue
V1.01.01	2. Fix audio noise issue 3. Support LED on/off on APP 4. Add tdb flush for fw upgrades from Gen1 to Gen2. 5. Fix ICR control issue

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A