**Firmware Version:** V1.03.09
**Prom Code Version:**
**Published Date:** 2015/5/15

## Content:

## Revision History and System Requirement:

| Firmware Version | Date | Model | Hardware Version |
|---|---|---|---|
| V1.00_b10 | 2014/6/16 | DCS-800L | A1 |
| V1.01_b3 | 2014/7/31 | DCS-800L | A1 |
| V1.02.06 | 2015/2/12 | DCS-800L | A1 |
| V1.03.09 | 2015/5/15 | DCS-800L | A1 |
| | | | |

## New Features:

| Firmware Version | New Features |
|---|---|
| V1.00_b10 | First formal release of DCS-800L firmware |
| V1.01_b3 | 1. Update mydlink agent to v2.0.17-b86<br>2. Add hardware version parameter for device info inquiry |
| V1.02.06 | 1. Update mydlink agent to v2.0.18-b61<br>2. Remove SSL and support TLS |
| V1.03.09 | 1. Update mydlink agent to v2.0.19-b35<br>2. Add Bonjour _dcamera service and remove Bonjour _http service |
| | |

## Problems Fixed:

| Firmware Version | Problems Fixed |
|---|---|
| V1.01_b3 | 1. Fixed the issue of some special characters (including space) displaying on Wi-Fi network list<br>2. Fixed the two-way audio issue that camera doesn't mute when talk function is enabled |
| V1.02.06 | 1. Fixed issue where device would not respond properly to portal commands under relay mode.<br>2. Fixed issue occurring randomly that could not live view on portal under relay mode. |
| V1.03.09 | 1. Fixed HTTPS issue that caused Day/Night control to not work properly.<br>2. Updated the time zone table list to support some existing time zones changes. |

| | |
|---|---|
| | 3. Fixed the issue that camera cannot connect to a Wireless Network with a Hidden SSID. <br> 4. Fixed CGI /reset.cgi reboot command issue. |
| | |

## Known Issues:

| Firmware Version | Known Issues |
|---|---|
| | |
| | |

## Related Documentation:

N/A

## Upgrading Instructions:

The notification of FW upgrade will be automatically delivered on mydlink portal and mydlink Baby Camera Monitor app when there is a new FW release. The camera will start upgrading to the new FW after users confirm to update.