Firmware Version: V1.04.03
Prom Code Version:
Published Date: 2019/6/24

Content:

Revision History:

Firmware Version	Agent Version	Date	Model	Hardware Version
V1.04.03	v 3.2.7-b01	2019/06/24	DCS-8525LH	A1
V1.03.06	v 3.2.3-b01	2019/04/3	DCS-8525LH	A1
V1.02.02	v3.0.0-b75	2018/08/14	DCS-8525LH	A1
V1.01.03	v3.0.0-b64.1	2018/05/29	DCS-8525LH	A1

System Requirement (minimum HW requirement):

System Requirements	mydlink APP for iPhone, iPad, Android phone and tablet.
Network Requirements	At least 1.5MB Byte upload bandwidth per camera.
Minimum Requirements	Compatible with iPhone and iPad using iOS 9 or higher Compatible with Android smartphones and tablets using Android 4.3 or higher

New Features:

Fireware Version	New Features
V1.04.03	1. Update mydlink agent to 3.2.7-b01. 2. Support smart push notification when received sound event.
V1.03.06	1. Update mydlink agent to v 3.2.3-b01 2. Support mydlink APP rich notification feature 3. Support mydlink APP fw manual upgrade feature 4. Support Micro SD cards up to 256GB. 5. PIN code as default password and setup by FW not factory. 6. Support D-Link Anti-Brute-Force Attack Mechanism_v04 7. Support WEP encryption 8. Set the PIN code as password after binding. 9. Support rtsp live stream over UDP, with Digest authertication
V1.02.02	1. Update mydlink agent to v3.0.0-b75 2. Support mydlink Requirements for IoT Agent Version 1.0.6
V1.01.03	1. Update mydlink agent to v3.0.0-b64.1 2. Change Video spec , 1080P up to 1.5M bitrate

Problems Fixed:

Firmware Version	Problems Fixed
V1.04.03	1. Remove TLS v1.0 and v1.1 support. 2. Fix camera shows offline few seconds status after binding finished.
V1.03.06	1. Fix device easy binding fail issue 2. Fix Bluetooth compatibility issue (D-track DGC20180706000002)
V1.02.02	1. Change IR cut minimum illumination. 2. Fix when sensitivity setup to 0%, it still can trigger motion detection.
V1.01.03	1. Reduce the echo noise on the device 2. Change PWR LED green on when LINK LED turn to green 3. Fix talk delay issue 4. Reduce video pixelization issue during PT moving

Known Issues:

Firmware Version	Known Issues
V1.03.06	The device status will show off-line for 2~3 second after first binding

Related Documentation:

N/A