DGS-1500 Series Firmware Patch Notes

Firmware: 2.51B021
Hardware: Ax
Date: October 4, 2017

Security Patch

Security Incident – Hard-coded password for shell access.
Fix - Hard-coded credentials have been removed.

- Reported: September 6, 2017 by: David Manouchehri

Security patch for your D-Link Devices

These firmware updates address the security vulnerabilities in affected D-Link devices. D-Link will update this continually and we strongly recommend all users to install the relevant updates.

As there are different hardware revisions on our products, please check this on your device before downloading the correct corresponding firmware update. The hardware revision information can usually be found on the product label on the underside of the product next to the serial number. Alternatively, they can also be found on the device web configuration.

Known Issues:
None