DIR-645 Firmware Release Notes

Firmware: FW1.04.B05 (Release)
Hardware: A1
Date: 2013/03/27

Note:
None

Problems Resolved: Security:

1. Solve the security issue that curl -H "Cookie: uid=9gIdu6X6nF" -d "EVENT=%26%20telnetd%26" http://192.168.0.1/service.cgi would cause script injection issue to execute telentd.

Enhancements:
None

Known Issues:
None

Firmware: FW1.04.B04 (BETA)
Hardware: A1
Date: 2013/03/25

Note:
None

Problems Resolved:

1. Fix: Reduce the logout timeout from ten to three minutes for D-Link request due to security consideration.

Enhancements:
None

Known Issues:
None

Firmware: FW1.04.B03 (BETA)
Hardware: A1
Date: 2013/03/22

Note:
None

Problems Resolved:

1. Security: Solve security problem that don't let version.php show too many router information without authentication.
2. Security: Solve security problem that turn off the widget function and remove the relative files like router_info.xml.
3. Security: Solve security problem that diable telnetd after the router is not longer factory default.

Enhancements:
None

Known Issues:
None

Firmware: FW1.04.B02 (BETA)
Hardware: A1
Date: 2013/03/22

Note:
None

Problems Resolved:

1. Fix: Ping for IPv6 ";reboot" will cause system reboot. We need do shell command escape before execute.
2. Fix: Resetting statistics would fail.
3. Fix: Signal of wifi client always show 100%
4. Security: 3 buffer overflow report from dlink.(post_login.xml, hedwig.cgi, authentication.cgi)
5. Security: (CSRF) Cross-site scripting on "bind.php"
6. Security: (CSRF) Cross-site scripting on "info.php"
7. Security: (CSRF) Cross-site scripting on "bsc_sms_send.php"
8. Security: Fix security problem that users could post any command to execute in the router by command.php.

Enhancements:

1. Add: 3TB hdd support

Known Issues:
None

Firmware: FW1.04.B01 (BETA)
Hardware: A1
Date: 2013/01/04

Note:
Ready firmware for next release, versioning, confirm software feature set

Problems Resolved:
None

Enhancements:
None

Known Issues:
None

Firmware: FW1.03 (Release)
Hardware: A1
Date: 2012/11/21

Note:
None

Problems Resolved:
None

Enhancements:

1. SharePort Mobile / Web access Support
2. Enhanced iOS6 compatibility
3. Enhanced IPv6

Known Issues:
None

Firmware: FW1.02 (Release)
Hardware: A1
Date: 2012/07/12

Note:
None

Problems Resolved:

1. Disable WPS-PIN Method

Enhancements:

1. Boxee improvement

Known Issues:
None

Firmware: FW1.01 (Release)
Hardware: A1
Date: 2011/09/26

Note:
None

Problems Resolved:

1. Fix wrong WAN port position picture in wizard setup.
2. Fix syslog function.
3. Fix DCS-5220 IPCAM WPA/WPA2 IOT issue.

Enhancements:
None

Known Issues:
None