DIR-655 Firmware Release Notes

Firmware: 3.02B05 BETA03
Hardware: Cx
Date: January 17, 2019

3rd Party Report:
In April 2018, a 3rd party research disclosed to D-Link 4 issues with the DIR-655 Rev. Cx.

by: Joel St. John (Joel.StJohn _at_ nccgroup _dot_ trust)

Issues Fixed:

1. Command injection via device configuration setting
2. Setup wizard can be used to reset password to default
3. Cross-site request forgery
4. Multiple reflected cross-site scripting issues

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.