DIR-818LW Firmware Patch Notes

Firmware: 2.06B01_BETA
Hardware: Bx
Date: January 4, 2019

Overview:
In November 2018, D-Link became aware of a 3rd Party security researcher that accused the DIR-860L Hardware Rev. Bx and DIR-818LW Series Hardware Revision Bx consumer routers of a remote command injection vulnerability.

After an investigation, this vulnerability is only accessible via the local-network (LAN-side) of the router and not directly from the Internet (WAN-side) since it requires access to the web browser configuration of the router.

3rd Party Report:
MinGeun Kim (pr0v3rbs _at_ kaist.ac.kr)
https://github.com/pr0v3rbs/CVE/tree/master/CVE-2018-20114

Problems Resolved:

CVE-2018-20114 - Unauthenticated OS Command Injection